

ASS. REC BY: Tau J M REF: CC4/41522.008663/Tr93.

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: 9250K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date/Time Action / Instruction

Veh No: SKF910L Yr Regn: 2021 / Aug

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Alphard C.C. 2493

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 24418 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AGH30036588U

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235 / 50 R18

R: 235 / 50 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A. _____ D.O.L. 8/9/22

Survey held at: Zoom Autoworks

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to? ☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

19 September 2022

REG NO.: SKF 910 L
MAKE/MODEL: TOYOTA ALPHARD

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

AMT(\$\$)

QTY	DESCRIPTION		AMT(\$\$)
	<u>LIST ITEMS</u>		
1	Front door -LH	\$	1,998.50 <i>Rx</i>
1	Front door checker	\$	85.60 <i>x</i>
2	Front door hinges	\$	179.00 <i>x</i>
1	Front door lock	\$	622.51 <i>x</i>
1	Front door rubber	\$	260.80 <i>x</i>
1	Front headlamp -LH	\$	5,845.20 <i>ant</i> 2,970.50
1	Front bumper	\$	1,337.21 <i>de</i>
1	Front bumper fog lamp	\$	220.70 <i>x</i>
1	Front bumper fog lamp chrome moulding	\$	285.80 <i>x</i>
1	Front bumper fog lamp cover	\$	120.30 <i>x</i>
1	Front bumper inner sponge	\$	130.80 <i>x</i>
1	Front bumper reinforcement	\$	300.80 <i>x</i>
1	Front bumper side retainer	\$	87.30 <i>de</i>
1	Front bumper side chrome moulding	\$	320.20 <i>ant</i>
1	Front bumper tow hook cover	\$	75.80 <i>x</i>
1	Front fender -LH	\$	1,248.80 <i>bt</i>
1	Front fender inner shield	\$	195.20 <i>de</i>
1	Front wheel hub with bearing	\$	501.30 <i>x</i>
1	Front shock absorber	\$	449.30 <i>x</i>
1	Front knuckle arm	\$	465.80 <i>x</i>
1	Front tie rod	\$	145.00 <i>x</i>
1	Front lower arm	\$	432.30 <i>x</i>
		\$	15,308.22
		Less 25%	3,827.06
		\$	11,481.17
	<u>SPECIAL NETT ITEMS</u>		
1	Front bumper clip (1 set)	\$	60.00 <i>3 ones</i>
1	Front tyre	\$	450.00 <i>x</i>
1	Front wheel rim -LH	\$	700.00 850.00 <i>ad</i>
		\$	1,360.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00 <i>30</i>
2	To remove and refit front undercarriage.	\$	350.00 <i>x</i>
3	To conduct wheel alignment.	\$	180.00 <i>x</i> 80
4	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	200.00 <i>x</i>
5	To apply undercoating.	\$	200.00 <i>40</i>
6	Panel beating.	\$	1,500.00 <i>600</i>
7	To re-spray painting on the affected areas.	\$	1,400.00 <i>750</i>
		\$	3,910.00

GRAND TOTAL:

\$ 16,751.17

Tanpin 97495749 up 8/1/22 e 2pm
 c/s Resurvey after repair
 Tanpin e/Chambers.com. 4 days.