



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7738E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	842.20	648.00
1	FRONT BUMPER N/S RETAINER	DEFORMED	137.25	80.00
1	FRONT BUMPER N/S FOG LAMP }	BROKEN	422.80	319.00
1	FRONT BUMPER N/S FOG LAMP BRACKET }		192.75	-
1	FRONT BUMPER N/S FOG LAMP GARNISH COVER	CUT	195.00	151.00
1	FRONT GRILLE	BROKEN	789.60	472.00
1	FRONT N/S HEAD LAMP	CRACKED	1,100.00	1,100.00
	LESS 25% DISCOUNT		-919.90	-692.50
			2,759.70	2,077.50
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
4	FRONT GRILLE CLIPS (SN)	NECESSARY	16.00	16.00
			56.00	46.00
	<u>LABOUR</u>			
	TO DISMANTLE, STRAIGHTEN & WELDING.		800.00	400.00
	TO SPRAY PAINTING.		600.00	400.00
	TO CHECK FOR FAULT CODE AND RE SET ELECTRICAL SYSTEM.	NOT NECESSARY	180.00	-
	TO CHECK WIRING.		50.00	30.00
	TO RE SEAL ANTI RUST.		50.00	20.00
			1,680.00	850.00
	GRAND TOTAL		4,495.70	2,973.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00

Report Ref No. CS/UOI22008672/Tvy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.