

ASS. REC BY: T. G. J. M.REF: CS/40122008072/703

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: **SLB 9228Z**

Policy No: \_\_\_\_\_

Claims No: **M12D19462209**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$68K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLG7738E Yr Regn: 2016, Out

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toyota Wish C.C. 1298Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 80375 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: STD6620WX05005488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 195/65R15R: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 4/9/2022D.O.I. 6/9/22Survey held at Ryder Auto.Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/1/23 Lump Sum \$2400 confirmed by email (Red 2095.70, 46%)

Date/Time, File Pass to?

☐ : Prel. Report

1) \_\_\_\_\_

☐ : Final Report

Date/Time, File Return to?

2) 12/1/23-typistRep. Format: TPLump Sum / L.B. / P. \$2400Days Of Repair: 3Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI. \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

## ESTIMATE OF REPAIR

Veh# SLG7738E

Accident Date 3/9/2022

Location SERANGOON NORTH BLK 108 CARPARK

Model: TOYOTA WISH 1.8

10/10/2016

3P: SLB9228Z (UOI)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper	842.20		all
2	10 pcs	Front bumper clips		40.00	all
3	1 pc	Front bumper n/s retainer	137.25		de
4	1 pc	Front bumper n/s fog lamp	422.80		?
5	1 pc	Front bumper n/s fog lamp garnish cover	195.00		int
6	1 pc	Front bumper n/s fog lamp bracket	192.75		?
7	1 pc	Front grille	789.60		?
8	4 pcs	Front grille clips		16.00	?
9	1 pc	Front n/s head lamp	1,100.00		eva
Sub Total:			3,679.60	56.00	0.00
			25%	0%	10%
After Less %:			2,759.70	56.00	0.00

Labour					
1		To dismantle, straighten & welding.	800.00	250	
2		To spray painting.	600.00	250	
3		To check for fault code and re set electrical system.	180.00	2	
4		To check wiring.	50.00	30	
5		To re seal anti rust.	50.00	X	
Sub Total:			1,680.00		
Total:			4,495.70		
After Less 20%:			3,596.56		

Chan San Choon  
Director  
DipEng, AAE MIM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any illegal modification(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

