

ASS. REC. BY:

REF:

Asm / 220086781Kp

C

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Thiam Heng Heng

of 6907

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 80k

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2-3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SGK 98280 Yr Regn: 10, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hundai Avante c.c. 1591

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 181287 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_ C/No: KM11D841CMLU010006

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modf: Nil / S/Rim / STD A/Rim or Tyre Size: F: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Turador

Front R/Bal. 5 mm Rear R/Bal. 3 mm

L/Bal. 5 mm L/Bal. 3 mm

D.O.A. 31/8/22 D.O.I. 6/9/2022

Survey held at \_\_\_\_\_ Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Make part by part, est not ready</u>
<u>8/9</u>	<u>UIC @ 1800 Cahri</u>

Date/Time, File Pass to?  : Prell. Report  : Final Report

1) \_\_\_\_\_ Date/Time, File Return to? 2) \_\_\_\_\_ Report Format : Lump Sum / I.B.I: (\$

Days Of Repair: \_\_\_\_\_ Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$  : Interview (\$  : Tech Invs (\$  : Weekend (\$

Survey Fee:
Transportation:
S - RS. SI
Fines
Others
TOTAL

Kp

# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HYUNDAI AVANTE

Engine/Chassis No.:

Date of accident: 31.08.22


Damaged area: Rear

*Not authorized  
11 Sep @ 1800h  
Recovery After Rainy*

Date: 06/09/2022

Claim Type: TP

VRN: SGK9828D



*4 days*

List items						
S/N	Parts description	QTY	UNIT PRICE	AMOUNT		
1	Rear Bumper <i>459.40</i>	<i>Per</i> 1	\$ 983.00	\$ 983.00		✓
2	Rear Bumper diffuser <i>265</i>	<i>Per/lot</i> 1	\$ 467.00	\$ 467.00		✓
3	Rear Bumper lower cowling	<i>Per</i> 1	\$ 314.00	\$ 314.00		X
4	Rear Bumper reflector <i>C 72.50</i>	<i>old mg com</i> 2	\$ 255.00	\$ 510.00		X
5	Rear Bumper splash guard	<i>Per</i> 2	\$ 95.00	\$ 190.00		X
6	Rear Bumper reinforcement support bracket	<i>DI 5-3</i>	\$ 36.00	\$ 180.00		✓
7	Rear Bumper reinforcement <i>341</i>	<i>Per</i> 1	\$ 659.00	\$ 659.00		✓
8	Rear Bumper reinforcement side bracket	<i>Per</i> 2	\$ 129.00	\$ 258.00		X
9	Rear bumper side retainer	<i>Per</i> 2	\$ 65.00	\$ 130.00		X
10	Rear licence plate lamp	<i>Per</i> 2	\$ 143.00	\$ 286.00		X
11	Rear bumper licence plate base	<i>Per</i> 1	\$ 59.00	\$ 59.00		✓
12	Taillamp	<i>Per</i> 2	\$ 561.00	\$ 1,122.00		X
13	Taillamp weatherseal	<i>Per</i> 2	\$ 16.00	\$ 32.00		X
14	End panel	<i>R</i> 1	\$ 732.00	\$ 732.00		X
15	End panel top garnish <i>62.90</i>	<i>mg com</i> 1	\$ 177.00	\$ 177.00		✓
16	Bootlid "AVANTE" emblem	<i>na</i> 1	\$ 53.00	\$ 53.00		X
17	Bootlid "Hyundai" logo	<i>na</i> 1	\$ 69.00	\$ 69.00		X
18	Bootlid	<i>R</i> 1	\$ 1,585.00	\$ 1,585.00		X
19	Bootlid inner trim	<i>Per</i> 1	\$ 149.00	\$ 149.00		X
20	Bootlid lock	<i>R</i> 1	\$ 324.00	\$ 324.00		X
21	Bootlid lock striker	<i>R</i> 1	\$ 56.00	\$ 56.00		X
22	Bootlid lamp	<i>Per</i> 2	\$ 479.00	\$ 958.00		X
				<b>Subtotal</b>	<b>\$ 9,293.00</b>	
				<b>List discount</b>	<b>20.00%</b>	
				<b>Total</b>	<b>\$ 7,434.40</b>	

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear Bumper clips <i>na</i>	12	\$ 4.50	\$ 54.00 ✓
2	Bootlid inner trim clips <i>na</i>	8	\$ 4.50	\$ 36.00 X
3	End panel top garnish clips <i>na</i>	8	\$ 4.50	\$ 36.00 X
4	Reverse sensor <i>short</i>	1	\$ 280.00	\$ 280.00 200na
5	End panel sealant <i>na</i>	1	\$ 100.00	\$ 100.00 X
6	Rear licence plate & frame <i>na</i>	1	\$ 55.00	\$ 55.00 45na ✓
7	Sundries <i>na</i>	1	\$ 50.00	\$ 50.00 X
<b>Total</b>				<b>\$ 611.00</b>

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00 450
2	To disconnect rear wire harness of electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00 20
3	To remove, replace reverse sensors and check for proper function.	0.5	\$ 100.00 50
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00 400
5	To rust proof accident affected portions.	0.5	\$ ~ 100.00 X
<b>Total labour</b>			<b>\$ 2,850.00</b>

<b>Estimate Grand Total</b>	<b>\$ 10,895.40</b>
-----------------------------	---------------------

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: