

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008692/UNY3Q2**Date:** 18/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00103522200

Claimant Vehicle No : SKC6082C **Insured Vehicle No :** SMZ9596Y

Date of Loss: 02/09/2022 Nature of Claim: TP Claim No: SNM22D206276/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC6082C**

Make & Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A) Engine No: G4FGBU306937

Reg. Date: 14/09/2011 (Man. Year: 2011) Chassis No: KMHDH41CMCU249497

Colour: Silver Odometer: 185974 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,407.08	1,957.60	3,449.48	63.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,330.00	600.00	31.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,337.08	3,287.60	4,049.48	55.19
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	7,337.08	2,600.00	4,737.08	64.56
+ GST 7.00/7.00% (S\$)	513.60	182.00	331.60	64.56
Nett Amount (S\$)	7,850.68	2,782.00	5,068.68	64.56

INSPECTION

Date of Assignment: 05/09/2022

Date Inspected: 27/09/2022 Inspected At: Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Oct 2022)

Parts: 143 HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKC6082C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER W/LOWER GARNISH -BLACK	Deformed / Cracked	460.00 FL	*460.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	49.00 FL	*49.00 FL
3	2		*REAR BUMPER SIDE HOLDER -RH/LH	Necessary	50.00 FL	*50.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Cracked	305.00 FL	*305.00 FL
5	2		*REAR BUMPER REINFORCEMENT BRACKET -RH/LH	Bent / Twisted	84.00 FL	*84.00 FL
6	2		*REAR BUMPER LAMP -LH/RH	Not fitted	58.00 FL	*- FL
7	1		*REAR BUMPER FOAM (NPA)	Not fitted	0.00 FL	*- FL
8	2		*REAR BUMPER BRACKET TOP -LH/RH	Twisted	22.00 FL	*22.00 FL
9	2		*REAR BUMPER BRACKETS LOWER -LH/RH	Twisted	22.00 FL	*22.00 FL
10	1		*REAR BOOT	Not Necessary	1,307.00 FL	*- FL
11	1		*REAR BOOT H LOGO	Not Necessary	29.00 FL	*- FL
12	2		*REAR BOOT HINGES -RH/LH	Not Necessary	190.00 FL	*- FL
13	1		*REAR BOOT HYUNDAI WORDING	Not Necessary	40.00 FL	*- FL
14	1		*REAR BOOT ELANTRA GLS WORDING	Not Necessary	38.00 FL	*- FL
15	1		*REAR BOOT TOP LOCK	Not Necessary	135.00 FL	*- FL
16	1		*REAR BOOT BOTTOM LOCK	Not Necessary	28.00 FL	*- FL
17	1		*REAR BOOT INSULATOR	Not Necessary	167.00 FL	*- FL
18	9		*REAR BOOT INSULATOR CLIPS	Not Necessary	44.10 FL	*- FL
19	1		*REAR PANEL ASSY	Dented / Bent	455.00 FL	*455.00 FL
20	1		*REAR PANEL TOP GARNISH	Not Necessary	65.00 FL	*- FL
21	2		*TAILLAMP CLIPS -LH/RH	Not Necessary	20.00 FL	*- FL
22	2		*TAILLAMP UNIT -LH/RH	Not Necessary	776.00 FL	*- FL
23	2		*TAILLAMP LOWER RETAINER -LH/RH	Not Necessary	344.00 FL	*- FL
24	2		*REAR NUMBER PLATE LAMP	Not Necessary	52.00 FL	*- FL
25	1		*REAR BOOT OUTER CHROME -CENTRE	Not Necessary	120.00 FS	*- FS
26	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	45.00 FS	*- FS
27	1		*SET REAR BUMPER SENSOR	Shorted	220.00 FS	*200.00 FS
28	1		*REAR BOOT CAMERA	Not Necessary	350.00 FS	*- FS
29	1		*REAR BUMPER TOP STICKER	Not Necessary	280.00 FS	*- FS
30	1		*REAR BUMPER LOWER SPOILER BLACK	Cracked	600.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,355.10	2,247.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	948.02	289.40
Total Parts (\$\$)	5,407.08	1,957.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS REMOVE REAR BOTH FENDER ,CUT /WELD REAR PANEL ,REPLACE ACCIDENT PARTS	New	800.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	600.00
3	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
4	TO CHECK WIRING	New	50.00	20.00
5	TO REMOVE ,REPAIR REAR EXHAUST PIPE	New	80.00	0.00
6	TO REMOVE,REFIX REAR GARNISH ,CARPET ,CUSHION & RELATED PARTS	New	100.00	60.00
Gross Labour Cost (\$\$)			1,930.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >