



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 7778Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT HEADLAMP RH (WCP)	CUT	1,600.00	1,600.00
1	FRONT BUMPER (WCP)	TO REPAIR SEE LABOUR	785.00	-
1	FRONT BUMPER SIDE RETAINER RH (WCP)	NOT NECESSARY	15.00	-
1	FRONT BUMPER FOGLAMP COVER RH (WCP)	NOT NECESSARY	48.00	-
1	FRONT BUMPER SENSOR RH (WCP)	NOT NECESSARY	98.00	-
1	FRONT BUMPER CHROME LOWER RH (WCP)	NOT NECESSARY	60.00	-
10	FRONT BUMPER RIVET @\$5.00 (WCP)	NOT NECESSARY	50.00	-
1	FRONT RIM (NPA) (WCP)	NOT NECESSARY	-	-
	COST PLUS 10%		265.60	160.00
			2,921.60	1,760.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING SYSTEM.		50.00	50.00
	TO CHECK ALIGNMENT.	NOT NECESSARY	100.00	-
	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		520.00	250.00
	SPRAYPAINTING CHARGES.		580.00	250.00
			1,250.00	550.00
	<b>GRAND TOTAL</b>		<b>4,171.60</b>	<b>2,310.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,310.00</b>

Report Ref No. CS/SMO22008693/Evy3q2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.