

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGX 77782 Yr Regn: 11/7/17
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes-Benz GLC 250 c.c. 1991
 Colour: Black A/C: ☒ Insured / Std / NI / NA
 Sp. Reading: 162378 T/Radio: ☒ Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDC2539462F240-706
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modl: Nil / ☒ Rim / STD AJRim or
 Tyre Size: F: 235/55R19
 R: 21
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 23/7/22 D.O.I. 6/9/22
 Survey held at Kan Fook Sing
 Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / ☒ Rooftop or
Front RH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>NR-143K</u>

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

1) Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.A. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)



簡福星嘢嘢王廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

SOMPO INSURANCE (S) PTE LTD

50 RAFFLES PLACE #03-03

SINGAPORE LAND TOWER

SINGAPORE 048623

VEHICLE NO. : SGZ7778Z

ACCIDENT DATE : 23-07-2022 11:30

THIRD PARTY REF. : SJP5636E

DATE : 05-08-2022

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SGZ7778Z MERCEDES MERCEDES BENZ GLC250 AMG 4MATI

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT HEADLAMP RH	1440.00
2	1	FRONT BUMPER	785.00
3	1	FRONT BUMPER SIDE RETAINER RH	15.00
4	1	FRONT BUMPER FOG LAMP COVER RH	48.00
5	1	FRONT BUMPER SENSOR RH	98.00
6	1	FRONT BUMPER CHROME LOWER RH	60.00
7	10	FRONT BUMPER RIVET @\$5.00	50.00
8	1	FRONT RIM (CHECK PRICE)	0.00
			2,496.00
ADD 10 %			249.60
TOTAL (A)			2,745.60

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	50.00
2	1	TO CHECK ALIGNMENT	100.00
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND F-ITTING NEW PARTS	520.00
4	1	SPRAYPAINTING CHARGES	580.00
TOTAL (D)			1,250.00

ESTIMATE TOTAL

3,995.60

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Price might be different due to stock availability