

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22008700/AVY3Q2
Date: 16/11/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00120172101	
Claimant Vehicle No :	SNF5018U	Insured Vehicle No :	GBE3020Y	
Date of Loss:	01/09/2022	Nature of Claim:	TP	Claim No: SNM22D206254/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF5018U	Engine No:	LEB7267732
Make & Model:	HONDA FREED, 1.5 (A)	Chassis No:	GB73156371
Reg. Date:	31/05/2022 (Man. Year: 2021)	Odometer:	18418 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,822.88	5,237.92	3,584.96	40.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	2,320.00	2,100.00	47.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,242.88	7,557.92	5,684.96	42.93
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	13,242.88	6,000.00	7,242.88	54.69

INSPECTION

Date of Assignment:	05/09/2022	
Date Inspected:	12/09/2022	Inspected At: JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2022)
Parts:	M1-MPV	HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF5018U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	925.30 FL	*828.00 FL
2	2		*REAR BUMPER CENTER BEAM	Not Necessary	279.40 FL	*- FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	85.60 FL	*- FL
4	1		*REAR BUMPER EXHAUST COVER GARNISH	Not Necessary	58.10 FL	*- FL
5	1		*REAR BUMPER TOWING COVER	Not Necessary	36.80 FL	*- FL
6	1		*REAR BUMPER INNER SIDE GARNISH	O/S Deformed	120.40 FL	*60.20 FL
7	2		*REAR BUMPER SIDE RETAINER (UPPER)	Not Necessary	79.40 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER (LOWER)	Damaged	84.60 FL	*84.60 FL
9	1		*REAR FENDER INNER TRIM	O/S Cracked	653.40 FL	*326.70 FL
10	1		*TAIL LAMP	O/S Cracked	1,160.80 FL	*580.40 FL
11	1		*TAIL LAMP PANEL RH	Dented	386.40 FL	*386.40 FL
12	1		*TAIL LAMP INNER PANEL RH	Repair	435.10 FL	*- FL
13	1		*TAIL LAMP LOWER PANEL RH	Repair	241.10 FL	*- FL
14	1		*TAIL LAMP INNER LOWER PANEL RH	Repair	336.80 FL	*- FL
15	1		*TAIL GATE	Dented	1,180.60 FL	*1,180.60 FL
16	1		*TAIL GATE LAMP	O/S Cracked	736.80 FL	*368.40 FL
17	1		*TAIL GATE LOGO	Necessary	59.20 FL	*59.20 FL
18	1		*TAIL GATE EMBLEM FREED	Necessary	52.30 FL	*52.30 FL
19	1		*TAIL GATE EMBLEM HYBRID	Necessary	75.70 FL	*75.70 FL
20	1		*TAIL GATE OUTER MOULDING (CHROME)	Cut	370.40 FL	*370.40 FL
21	1		*SET TAIL GATE DAMPER (ELECTRONIC)	Not Necessary	120.10 FL	*- FL
22	2		*TAIL GATE STOPPER	Not Necessary	26.40 FL	*- FL
23	1		*TAIL GATE WEATHERSTRIP	Cut	168.70 FL	*168.70 FL
24	1		*TAIL GATE INNER TRIM	Cracked	295.30 FL	*295.30 FL
25	1		*TAIL GATE TOP LOCK	Damaged	157.60 FL	*157.60 FL
26	1		*TAILGATE LOWER LOCK	Damaged	26.70 FL	*26.70 FL
27	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	145.70 FL	*145.70 FL
28	1		*REVERSE CAMERA	Not Necessary	786.90 FL	*- FL
29	1		*REAR END PANEL (OUTER)	Dented	623.70 FL	*623.70 FL
30	1		*REAR END PANEL TOP GARNISH	Deformed	169.30 FL	*169.30 FL
31	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
32	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
33	1		*SET TAILLAMP CLIP	Necessary	40.00 FS	*20.00 FS
34	1		*SET TAIL GATE OUTER MOULDING CLIP	Necessary	50.00 FS	*20.00 FS
35	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
36	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*30.00 FS
38	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
39	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
40	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
41	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

11/16/22, 3:13 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	10,798.60	6,429.90
					- List Item Discount on L Items 20.00/20.00% (\$)	1,975.72	1,191.98
					Total Parts (\$)	8,822.88	5,237.92
Report was unsubmitted during this print-out.							

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,WELDING ,CUTTING GRAZING ADJUST KNOCK STRAIGHTEN	New	1,800.00	900.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,200.00	900.00
3	TO APPLY RUST PROOFING /UNDER COAT	New	250.00	80.00
4	WIRNING BULB CHECKING	New	80.00	30.00
5	REMOVE AND REFIX UPHOLSTERY CUSHION SEAT TO FACILITATE REPAIR	New	350.00	80.00
6	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
9	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
10	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
11	REMOVE AND REFIX CAR VIDEO RECORDER	New	80.00	50.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,420.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >