



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 745C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BUCKLED	773.00	773.00
1	FRONT BUMPER LOWER GARNISH	SERVICEABLE	468.00	-
10	FRONT BUMPER CLIP	NECESSARY	35.00	35.00
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	36.00	36.00
1	HEADLAMP LH	CUT	2,885.00	2,785.00
1	FOG LAMP LH	SERVICEABLE	662.00	-
1	FOG LAMP COVER LH	MTG CRACKED	115.00	115.00
1	LH FRONT FENDER	BUCKLED	653.00	653.00
1	LH FRONT FENDER UNDERSHIELD	SERVICEABLE	115.00	-
10	LH FRONT FENDER UNDERSHIELD CLIP	NOT NECESSARY	35.00	-
1	LH FRONT LOWER ARM	SERVICEABLE	448.00	-
1	LH FRONT SHOCK ABSORBER	SERVICEABLE	428.00	-
1	LH FRONT SHOCK ABSORBER TOP MOUNTING	SERVICEABLE	65.00	-
1	LH FRONT KNUCKLE ARM	SERVICEABLE	405.00	-
1	LH FRONT KNUCKLE BEARING }	NOT NECESSARY	554.00	-
1	LH FRONT WHEEL HUB }		-	-
1	LH FRONT TIE ROD	SERVICEABLE	115.00	-
1	LH FRONT TIE ROD END	SERVICEABLE	98.00	-
1	LH FRONT DRIVE SHAFT	TO REPAIR SEE LABOUR	898.00	-
1	HEADLAMP LH	REPEATED	2,885.00	-
1	HEADLAMP GARNISH LH (ADDITIONAL)	CRACKED	75.00	75.00
1	FRONT UPPER GRILLE SIDE GARNISH LH (ADDITIONAL)	DENTED	53.00	53.00
1	FRONT BUMPER INNER AIR DUCT (ADDITIONAL)	CRACKED	47.00	47.00
	LESS 10% DISCOUNT		-1,184.80	-457.20
			10,663.20	4,114.80
<u>SPECIAL NETT ITEMS</u>				
1	LH FRONT RIM (SN)	DENTED	380.00	380.00
1	LH FRONT TYRE (SN)	SERVICEABLE	350.00	-
			730.00	380.00

Report Ref No. CS/SMR22008702/Kqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, LHF FENDER, LHF DOOR). INCLUSIVE OF THE REPAIR OF LH FRONT DRIVE SHAFT.		1,000.00	400.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER, LHF FENDER, LHF DOOR).		800.00	400.00
	TO CHECK WIRING, FOCUS HEADLAMP.		50.00	20.00
	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.	NOT NECESSARY	250.00	-
	TO DO WHEEL ALIGNMENT.		120.00	60.00
	TO TUFF COAT.		50.00	30.00
			2,270.00	910.00
	GRAND TOTAL		13,663.20	5,404.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00

Report Ref No. CS/SMR22008702/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.