

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008713/ECE2**Date:** 01/02/2023REFERENCE

Insured/Claimant:	TOH TECK KIONG	Policy No:	7220030428	
Date of Loss:	01/09/2022	Nature of Claim:	OD	Claim No: 3490420944SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ173E	Engine No:	DEM035964
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF58NA010536
Reg. Date:	25/03/2022 (Man. Year: 2021)	Odometer:	9606 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$230,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/30Z R20	Rear Tyre Size:	275/30Z R20
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,437.00	19,699.28	30,737.72	60.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,724.00	9,444.00	10,280.00	52.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	70,161.00	29,143.28	41,017.72	58.46
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	69,361.00	28,343.28	41,017.72	59.14
+ GST 8.00/8.00% (S\$)	5,548.88	2,267.46	3,281.42	59.14
Nett Amount (S\$)	74,909.88	30,610.74	44,299.14	59.14

INSPECTION

Date of Assignment:	05/09/2022	
Date Inspected:	05/09/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	11.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIP	Necessary	79.00 FS	*63.20 FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Broken	293.00 FS	*234.00 FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	599.00 FS	*- FS
6	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	144.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	293.00 FS	*- FS
8	2		*RADIATOR AIR GUIDE GRILLE - LH / RH	Not Necessary	302.00 FS	*- FS
9	2		*RADIATOR AIR GUIDE GRILLE OUTER TRIM - LH / RH	Not Necessary	108.00 FS	*- FS
10	1		*RADIATOR GRILLE TRIM - CENTER	Not Necessary	127.00 FS	*- FS
11	1		*RADIATOR GRILLE	Broken	1,881.00 FS	*1,504.80 FS
12	1		*RADIATOR GRILLE COVER CAP	Missing	141.00 FS	*112.40 FS
13	1		*RADIATOR GRILLE BRACKET	Broken	19.00 FS	*14.64 FS
14	1		*FRONT CAMERA	Not Necessary	1,264.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	163.00 FS	*130.40 FS
16	1		*FRONT BUMPER CARRIER	Bent	899.00 FS	*719.20 FS
17	2		*FRONT BUMPER BRACKET - LH / RH	Broken	508.00 FS	*406.40 FS
18	1		*FRONT BUMPER GUIDE SECTION - LH / RH	O/S Broken	82.00 FS	*32.24 FS
19	1		*FRONT BUMPER TOP COVER	Crushed	143.00 FS	*114.00 FS
20	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
21	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
22	1		*LOCK CARRIER	Broken	154.00 FS	*122.80 FS
23	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*51.04 FS
24	4		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	1,062.00 FS	*- FS
25	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
26	1		*SET FRONT BUMPER WIRING	Not Necessary	449.00 FS	*- FS
27	1		*HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
28	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
29	2		*HORN BRACKET - LH / RH	Not Necessary	66.00 FS	*- FS
30	2		*FRONT FENDER - LH / RH	Not Necessary	2,378.00 FS	*- FS
31	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
32	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	166.00 FS	*- FS
33	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	82.00 FS	*- FS
34	11		*FRONT FENDER RIVET	Not Necessary	42.00 FS	*- FS
35	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	264.00 FS	*- FS
36	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	598.00 FS	*- FS
37	1		*FRONTWHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	176.00 FS	*- FS
38	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	164.00 FS	*- FS
39	1		*BONNET	Dented	3,491.00 FS	*2,792.80 FS
40	1		*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
41	2		*BONNET HINGE - LH / RH	Not Necessary	932.00 FS	*- FS
42	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
43	1		*BONNET SOUND ABSORBER	Crushed	382.00 FS	*305.60 FS
44	1		*BONNET BOWDEN CABLE - CENTER	Torn	64.00 FS	*50.56 FS
45	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
46	1		*BONNET BOWDEN CABLE - CENTER	Bent	64.00 FS	*50.56 FS
47	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
48	2		*BONNET STRIKER - LH / RH	Bent	112.00 FS	*89.12 FS
49	2		*BONNET LOCK	Bent	455.00 FS	*364.00 FS
50	2		*FRONT FENDER TOP LEDGE COVER - LH / RH	Not Necessary	80.00 FS	*- FS
51	2		*FRONT FENDER INNER LEDGE COVER - LH / RH	Broken	98.00 FS	*77.28 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*HEADLIGHT - LH / RH	Broken (1Pc Only)	16,344.00 FS	*6,537.60 FS
53	1		*HEADLIGHT HOSE	Not Necessary	42.00 FS	*- FS
54	2		*HEADLIGHT COMPENSATING PIECE	Necessary	90.00 FS	*71.04 FS
55	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	47.00 FS	*- FS
56	1		*LIFT CYLINDER BRACKET - RH	Not Necessary	17.00 FS	*- FS
57	2		*LIFT CYLINDER - LH / RH	Not Necessary	434.00 FS	*- FS
58	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
59	1		*LOCK CARRIER	Broken	1,478.00 FS	*901.60 FS
60	2		*COOLANT REGULATOR SUPPORT - LH / RH	Not Necessary	85.00 FS	*- FS
61	1		*AIR COOLER CHARGE	Not Necessary	654.00 FS	*- FS
62	1		*A/C CONDENSER	Bent	683.00 FS	*546.00 FS
63	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	186.00 FS	*- FS
64	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	381.00 FS	*- FS
65	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	277.00 FS	*- FS
66	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
67	1		*RADIATOR	Necessary	699.00 FS	*558.80 FS
68	1		*RADIATOR COOLANT FAN RING	Broken	277.00 FS	*221.20 FS
69	1		*RADIATOR FAN CONTROL UNIT	Not Necessary	2,012.00 FS	*- FS
70	2		*RADIATOR AIR GUIDE - LH / RH	Broken	72.00 FS	*56.80 FS
71	2		*RADIATOR AIR GUIDE - LH / RH	Broken	38.00 FS	*29.28 FS
72	1		*RADIATOR AIR GUIDE - UPPER	Crushed	19.00 FS	*14.64 FS
73	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
74	6		*READY-MIX COOLANT	Necessary	297.00 FS	*237.12 FS
75	1		*INTAKE AIR DUCT - RH	Broken	25.00 FS	*19.68 FS
76	1		*INTAKE AIR DUCT AIR GUIDE	Broken	61.00 FS	*48.48 FS
77	1		*INTAKE AIR DUCT HOSE	Broken	110.00 FS	*88.00 FS
78	1		*AIR FILTER	Not Necessary	418.00 FS	*- FS
79	1		*FRONT FENDER TRIM - LH / RH	O/S Necessary	342.00 FS	*136.40 FS
80	1		*FRONT DOOR TRIM - LH / RH	N/S Necessary	342.00 FS	*136.40 FS
81	2		*FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH	Not Necessary	892.00 FS	*- FS
82	1		*FRONT ROOF MOLDING - LH / RH	O/S Torn	1,412.00 FS	*564.80 FS
83	2		*FRONT WATER DEFLECTOR STRIP - LH / RH	Not Necessary	150.00 FS	*- FS
84	2		*FRONT FENDER PROTECTION FILM - LH / RH	Not Necessary	40.00 FS	*- FS
85	1		*FRONT NO PLATE	Bent	150.00 FS	*150.00 FS
86	1		*SUNDRIES	Necessary	500.00 FS	*43.44 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **50,437.00** **19,699.28**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARHE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,600.00	1,600.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO REMOVE AND REINSTALL BOTH DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	560.00	280.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	2,500.00
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLAR	New	7,500.00	2,750.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (S\$)			19,724.00	9,444.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >