

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22008721/TCY3Q2**Date:** 02/03/2023**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP317456
Claimant Vehicle No :	SMN8384L	Insured Vehicle No :	SKW349T
Date of Loss:	02/09/2022	Nature of Claim:	TP
		Claim No:	MPC03647/GN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN8384L	Engine No:	1ZZ2633524
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100316396
Reg. Date:	05/07/2006 (Man. Year: 2006)	Odometer:	370028 km
Colour:	Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R16	Rear Tyre Size:	185/60 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,078.61	2,628.89	1,449.72	35.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,520.00	1,020.00	40.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,618.61	4,148.89	2,469.72	37.31
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	6,618.61	3,300.00	3,318.61	50.14
+ GST 8.00/8.00% (S\$)	529.49	264.00	265.49	50.14
Nett Amount (S\$)	7,148.10	3,564.00	3,584.10	50.14

INSPECTION

Date of Assignment:	06/09/2022		BLK 3007 UBI ROAD 1
Date Inspected:	06/09/2022	Inspected At:	#01-434
			SINGAPORE 408701
			Repairer: KAI MOTOR TRADING (HQ)
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN8384L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Bent	1,061.30 FL	*1,061.30 FL
2	1		*REAR BOOT COVER LOGO	Necessary	75.10 FL	*75.10 FL
3	1		*REAR BOOT COVER MOULDING	Not Necessary	110.20 FL	*- FL
4	1		*REAR WINDSCREEN GLASS SEAL	Necessary	55.10 FL	*55.10 FL
5	1		*REAR BOOT COVER INNER LOCK	Bent	359.40 FL	*359.40 FL
6	1		*REAR BOOT COVER INNER RUBBER	Cut	399.15 FL	*338.20 FL
7	1		*REAR LAMP	N/S Necessary/O/SNot Necessary	802.70 FL	*401.35 FL
8	1		*REAR PANEL	Repair	519.40 FL	*- FL
9	1		*REAR PANEL INNER GARNISH	Deformed	201.40 FL	*201.40 FL
10	1		*REAR BUMPER	Deformed	695.40 FL	*590.00 FL
11	10		*REAR BUMPER CLIPS	Necessary	150.00 FL	*30.00 FL
12	1		*REAR BUMPER SIDE RETAINER	N/S Deformed /O/S NotNecessary	220.70 FL	*60.00 FL
13	2		*REAR BUMPER REFLECTOR	Not Necessary	132.20 FL	*- FL
14	1		*REAR LAMP LOWER BRACKET LH	Not Necessary	56.10 FL	*- FL
15	1		*REVERSE SENSOR	Not Working	380.00 FS	*200.00 FS
16	1		*WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,288.15	3,421.85
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,209.54	792.96
Total Parts (\$\$)	4,078.61	2,628.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLAE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY	New	950.00	600.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION	New	1,100.00	700.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
4	TO SPRAY PUFF COST	New	150.00	40.00
5	TO REMOVE REVERSE SENSOR	New	120.00	30.00
6	TO CHECK WIRING FUNCTIONS	New	100.00	30.00
Gross Labour Cost (S\$)			2,540.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >