4/19/23, 12:39 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS22008725/GEA3Q2

19/04/2023 Date:

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF100000538

Claimant Vehicle SHC1333Y Insured Vehicle No: GBE6269C

No:

Date of Loss: 02/09/2022 Nature of Claim: TP Claim No: SVRAISCL2022-00051

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC1333Y**

TOYOTA PRIUS, 1.8 HYBRID CVT (A) 2ZRS054110 Make & Model: Engine No:

Reg. Date: 19/07/2017 (Man. Year: 2017) Chassis No: JTDKB3FU403560567

Colour: Blue Odometer: 0 km

Engine Capacity: 1798 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,323.53	1,271.08	2,052.45	61.76
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,410.00	630.00	780.00	55.32
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,733.53	1,901.08	2,832.45	59.84
	Approved Total (Overridden) (S\$)		1,500.00		
	Nett Amount (S\$)	4,733.53	1,500.00	3,233.53	68.31
	Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 06/09/2022

ComfortDelGro Engineering Pte Ltd (Loyang) 06/09/2022 Inspected At: 59 Loyang Drive Date Inspected:

Singapore 508969

Estimated Period of Repair: 2.0 days

XING GUO QIANG **CHEW HSIAO TONG** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2023)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC1333Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FRONT BUMPER	Deformed	586.18 FL	*586.18 FL
2	1		*LAMP ASSY FOG RH	Cut	910.20 FL	*910.20 FL
3	1		*UNIT ASSY HEADLAMP RH	Not Necessary	2,637.60 FL	*- FL
4	10		*BUMPER PIECE	Not Necessary	22.00 FL	*- FL
5	1		*LINER FRONT FENDER RH	Torn	198.40 FL	*198.40 FL
6	1		*SUPPORT FRONT BUMPER SIDE	Not Necessary	77.00 FL	*- FL
F=Fra	nchise	part. L=ListIter	nDisc.	Sub Total (S\$)	4,431.38	1,694.78
			- List Item Discount o	1,107.85	423.70	
				Total Parts (S\$)	3,323.53	1,271.08
			Report was unsubmitted	I during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	750.00	350.00
2	SPRAYPAINT CHARGE	New	600.00	250.00
3	CHECK ALL LIGHTING	New	60.00	30.00
		Gross Labour Cost (S\$)	1,410.00	630.00
	R	eport was unsubmitted during this print-out.		

< END OF ESTIMATES >