



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBH 7610C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT)	CRACKED	545.00	545.00
2	REAR BUMPER RETAINER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER N/PLATE LAMP (CONSISTENT)	CRACKED	187.30	187.30
2	REAR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	450.60	450.60
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	607.34	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	CRACKED	129.09	129.09
1	REAR END PANEL WHETHER STRIP (CONSISTENT)	TORN	217.50	150.00
	LESS 25% DISCOUNT		-	-365.50
			2,136.83	1,096.49
	<b><u>LABOUR</u></b>			
	PANEL BEAT. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	400.00
	RESPRAY PAINT.		800.00	400.00
	RUST PROOF.	NOT NECESSARY	100.00	-
			1,700.00	800.00
<b>GRAND TOTAL</b>			<b>3,836.83</b>	<b>1,896.49</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,500.00</b>

Report Ref No. CS/ASM22008726/Svy3m4

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.