

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO22008731/Uqy3m4 Ref: 50 RAFFLES PLACE #03-03 Date: 23/09/2022 SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SLC 2437C SMA 4655A Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. CMTD2203101/RUC Excess (\$) 0.00 **GRACE TEO Assign Date** 06/09/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA COROLLA ALTIS (A) c.c Make & Model 1598 HIDDEN 2016 Engine No. Year of Reg. MR053REH104547571 SILVER Chassis No. Colour 110720 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 205/55 R16 DELIUM 6 mm DELIUM L/H Front Tyre 205/55 R16 6 mm 205/55 R16 DELIUM R/H Rear Tyre 6 mm **DELIUM** L/H Rear Tyre 205/55 R16 6 mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION & N/S 5. **General Information** 31/08/2022 06/09/2022 ( 01:42 PM ) Inspect Date / Time Accident Date YAP MOTOR COMPANY Survey held at BLK 3020A UBI ROAD 1 #01-38 SINGAPORE 408714 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS

Report Ref No. CS3/SMO22008731/Ugy3m4

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

**Estimate Days of Repair** 

**Inspected By** 

5b.

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

ESTIMATED NORMAL PERIOD FOR REPAIR:

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days