

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22008733/UQY3E2**Date:** 14/10/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:  
**Claimant Vehicle No :** FBR507L **Insured Vehicle No :** SMZ1022P  
 Date of Loss: 31/08/2022 Nature of Claim: TP Claim No: DMPC2200392H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR507L**  
 Make & Model: HONDA ADV150, 149cc ABS CVT Engine No: KF61E1007073  
 Reg. Date: 05/02/2020 (Man. Year: 2019) Chassis No: MH1KF6111KK007073  
 Colour: Grey Odometer: 52851 km  
 Engine Capacity: 149 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-14 Rear Tyre Size: 140/60-13  
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,450.10	2,290.40	4,159.70	64.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	350.00	630.00	64.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,430.10</b>	<b>2,640.40</b>	<b>4,789.70</b>	<b>64.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,430.10</b>	<b>2,100.00</b>	<b>5,330.10</b>	<b>71.74</b>

INSPECTION

Date of Assignment: 06/09/2022  
 Date Inspected: 07/09/2022 Inspected At: Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)  
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit  
 Singapore 417883  
 Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 14 Oct 2022)	
<b>Parts:</b>	N/A	HONDA ADV150 149cc ABS CVT (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBR507L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	168.00 FL	*128.00 FL
2	2		*FRONT FORK TUBE ASSY	Serviceable	680.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Not Necessary	220.00 FL	*- FL
4	1		*FRONT SIGNALS N/S	Cracked	216.00 FL	*100.00 FL
5	1		*HANDLE BAR	Not Necessary	180.00 FL	*- FL
6	1		*HANDLE BAR BALANCER N/S	Cut	98.00 FL	*30.00 FL
7	1		*SET HAND GRID	Not Necessary	58.00 FL	*- FL
8	1		*MIRROR	Cracked	110.00 FL	*80.00 FL
9	1		*BRAKE LEVER N/S	Cut	130.00 FL	*98.00 FL
10	1		*WINDSCREEN	Cut	225.00 FL	*225.00 FL
11	1		*FOOT STEP PANEL	N/S Cut	310.00 FL	*155.00 FL
12	1		*FOOT STEP LOWER PANEL	N/S Cut	350.00 FL	*170.00 FL
13	1		*FRONT SIDE FAIRING	N/S Cut	360.00 FL	*140.00 FL
14	1		*EXHAUST ASSY	Not Necessary	860.00 FL	*- FL
15	1		*EXHAUST FRONT COVER	Not Necessary	85.00 FL	*- FL
16	1		*EXHAUST CENTRE COVER	Not Necessary	108.00 FL	*- FL
17	1		*EXHAUST END CAP	Not Necessary	95.00 FL	*- FL
18	1		*SIDE STAND	Cut	165.00 FL	*120.00 FL
19	1		*MAIN STAND	Cut	225.00 FL	*160.00 FL
20	1		*AIR FILTER ASSY	Cut	328.00 FL	*250.00 FL
21	1		*BELT HOUSING	Cut	428.00 FL	*300.00 FL
22	1		*SET NUMBER PLATE	Frnt Necessary	38.00 FS	*10.00 FS
23	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
24	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
25	1		*BEARING CONE	Not Necessary	95.00 FS	*- FS
26	1		*REAR BOX	Cut	580.00 FS	*400.00 FS
27	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
28	1		*HEADLAMP PROTECTOR	Not Necessary	240.00 FS	*- FS
29	1		*SIDE STAND BIGFOOT	Cut	60.00 FS	*40.00 FS
30	1		*FOOTSTEP BOARD PROTECTOR	N/S Cut	192.00 FS	*80.00 FS
31	1		*STICKER	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>6,990.00</b>	<b>2,486.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	539.90	195.60
<b>Total Parts (S\$)</b>	<b>6,450.10</b>	<b>2,290.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO RESPRAY PAINT	New	420.00	0.00
3	TO PROVIDE LABOUR	New	480.00	350.00
			<b>Gross Labour Cost (\$)</b>	<b>980.00</b>
				<b>350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >