



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22008735/Avy3e2 Date: 27/02/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 3408P	Veh. Inspected	YQ 10K	
Policy No.	D-22099187MFBP	Coverage (\$)	0.00	
Claim No.	D22002816MFBP	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	06/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER FEB21ER4SDEN	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	FEB21EA30011	Colour	WHITE	
Odometer	161486 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	KENDA	6 mm	
L/H Front Tyre	195/85 R15	KENDA	6 mm	
R/H Rear Tyre	195/85 R15 (D)	KENDA	6/6 mm	
L/H Rear Tyre	195/85 R15 (D)	KENDA	6/6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	04/09/2022	Inspection Date	17/10/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	