

Steve

CS/EG122008747/Eng3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XE 6041C Yr Regn: 14/12/90
 Type: Truck / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Make: Hino FSTEKNID c.c. 12,913
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 184689 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHDF SIE KNXXX 10093
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD / Rrim or
 Tyre Size: F: 295/80R22.5
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Sailun

Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 3/18/22 D.O.I. 7/9/22

Survey held at V-KIX

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MIV-185K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.H. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + R.S. \$ _____

Photos

Others

TOTAL



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE

DATE

6/9/2022

SHEET NO. 1 OF 1 SHEET

Attention: Motor Claim Department

RE : VEHICLE NO : XE6051C Hino 700

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	1	FRONT BUMPER ASSY		2,659.00
2	1	FRONT HEADLAMP RH ASSY		1,859.00
3	1	FRONT HEADLAMP RH BRACKET		1,125.00
4	1	FRONT FOOT STEP LOWER GARNISH RH		789.00
5	1	FRONT FOOT STEP REFLECTOR		138.00
6	1	FOOT STEP STEEL PLATE		325.00
7	1	FOOT STEP EXTENSION RH		1,568.00

15% DIS

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S\$
1	1	To remove damaged body parts with all necessary components/ attachment apply hot-works where necessary straighten front floor panel repair, reshape body dented panel in accordance to factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,200.00 300
2	1	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	1,000.00 400
3	1	Wiring and bulb checking	150.00 30

WENG SHENG

KOH WENG SHENG

NAME, SIGNATURE, DATE SIGNED

Stem (LKK)
7/9/22, 10.10am

W R
L S
M AL
3 JY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: