

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 1104S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | RH ROCKER PANEL | NOT NECESSARY | 2,400.00 | - |
| 1 | REAR RH SLIDING DOOR | TO REPAIR SEE LABOUR | 2,160.00 | - |
| 1 | REAR RH FENDER | TO REPAIR SEE LABOUR | 2,400.00 | - |
| 1 | REAR BUMPER | CUT | 720.00 | 720.00 |
| 1 | REAR RH BUMPER SIDE RETAINER | NOT NECESSARY | 72.00 | - |
| 1 | REAR RH WHEEL RIM COVER | CUT | 240.00 | 240.00 |
| 1 | RH TAILLAMP | NOT NECESSARY | 288.00 | - |
| | LESS 30% DISCOUNT | | -2,484.00 | -288.00 |
| | | | 5,796.00 | 672.00 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET REAR BUMPER CLIPS (SN) | NECESSARY | 60.00 | 30.00 |
| 1 | FRONT RH TYRE (SN) | NOT NECESSARY | 350.00 | - |
| | | | 410.00 | 30.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEAT, CUT, WELD, RE-ALIGN & REPLACE DAMAGED PARTS OF AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR RH SLIDING DOOR AND REAR RH FENDER. | | 850.00 | 400.00 |
| | PUTTY, BLEND AND SPRAY PAINT ON AFFECTED AREA. | | 720.00 | 400.00 |
| | CHECK WIRING, RE-ALIGN TAILLAMP AND ENSURE PROPER FUNCTIONING. | | 80.00 | 30.00 |
| | CHECK, RE-ADJUST AND COMPUTERISE WHEEL ALIGNMENT / SIDE SLIP TEST. | | 180.00 | 60.00 |
| | REMOVE, REPLACE AND BALANCE RIM / TYRE. (PER RIM) | | 40.00 | 20.00 |
| | CHECK, RE-ADJUST AND COMPUTERISE WHEEL ALIGNMENT / SIDE SLIP TEST. | NOT NECESSARY | 180.00 | - |
| | REMOVE AND REINSTALL 2/4 PIECE OF BUMPER SENSORS. | | 120.00 | 30.00 |

Report Ref No. CS/INC22008759/Ecy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---------------------------------------------------|---------------|-------------------------------|-------------------|
| | REMOVE, REPLACE AND BALANCE RIM / TYRE. (PER RIM) | NOT NECESSARY | 40.00 | - |
| | | | 2,210.00 | 940.00 |
| | GRAND TOTAL | | 8,416.00 | 1,642.00 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 1,300.00 |
|---------------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | |

Report Ref No. CS/INC22008759/Ecy3e2



Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.