



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 2210S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR RH (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	FRONT RH CORNER PANEL (CONSISTENT)	MTG CRACKED	650.00	505.14
1	FRONT CENTER PANEL (NPA)(CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	SIGNAL LAMP RH (CONSISTENT)	CRACKED	580.00	263.60
1	HEADLAMP RH (CONSISTENT)	MTG CRACKED	986.00	628.91
1	FRONT GRILLE (CONSISTENT)	SERVICEABLE	588.00	-
1	FRONT BUMPER RH GARNISH (CONSISTENT)	SERVICEABLE	385.00	-
	LESS 25% DISCOUNT		-797.25	-349.41
			2,391.75	1,048.24
	<u>LABOUR</u>			
	LABOUR CHARGES REPAIR ,REPLACE ,ALIGN ADJUST ETC.INCLUSIVE OF THE REPAIR OF FRONT DOOR RH AND FRONT CENTER PANEL .		600.00	200.00
	TO DO ANTI RUST.	NOT NECESSARY	90.00	-
	CHECK LAMP WIRING SYSTEM ,FORCUS HEADLAMP.		120.00	20.00
	TO DO SPRAY PAINTING ON AFFECTED AREA INNER OUTER .		600.00	120.00
			1,410.00	340.00
GRAND TOTAL			3,801.75	1,388.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CC4/ASM22008760/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.