



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LOW GARNET			Ref: CS/ASM22008763/Avy3e2 Date: 16/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SND 852X	Veh. Inspected	SCV 3338E
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M04ABW	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	06/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2001
	Chassis No.	JTDBZ22E103000025	Colour	BLUE
	Odometer	183343 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	MICHELIN	6 mm
	L/H Front Tyre	195/55 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/55 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/55 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/09/2022	Inspection Date	08/09/2022
	Survey held at	Blk 51, Paya Ubi Industrial Park Ubi Avenue 1 #01-25		
	Repairer	T & C AUTOMOTIVE		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	