

SCV 3338E.

Toyota Corolla

JTDBZ22E103000025

|                                   |           |                        |          |
|-----------------------------------|-----------|------------------------|----------|
| Rear Bumper                       | Debond    | 456                    | ✓        |
| Rear Bumper Clips.                | New       | 30 (SN)                | ✓        |
| Rear Bumper Side Holder x 02      | LH<br>RH  | <del>35 x 2 = 70</del> | 35       |
| Rear Bumper Impact Bracket x 02   | Dented    | 61                     | ✓        |
| Reverse Sensor                    | Damaged   | <del>280 (SN)</del>    | 200 (SN) |
| Rear End Panel                    | Dented.   | 485                    | ✓        |
| Rear End Panel Top Garnish        | HP<br>New | 185                    | X.       |
| Rear End Panel Top Garnish Clips. | New       | 20 (SN)                | ✓        |
| Rear End Panel Sealant            | New       | 60 (SN)                | ✓        |
| Taillamp LH.                      | cracked   | 293                    | ✓        |
| Taillamp Panel LH.                | Repair    | 109                    | X        |

# SCV3338E.

|                               |                 |                 |      |
|-------------------------------|-----------------|-----------------|------|
| Bootlid                       | Regis           | 599             | X    |
| Bootlid Lock                  | NH nec          | 122             | X    |
| Bootlid Weatherstripe.        | NH nec          | 175             | X.   |
| 1-6 GLI Emblem.               | Nec             | 60              | ✓    |
| Toyota Wording.               |                 | 48              | ✓    |
| Corolla Wording               |                 | 45              | ✓    |
|                               | 1458            | S.N: 310        |      |
|                               | km 25%: 1093.50 |                 |      |
| Panel Beating                 |                 | <del>1000</del> | 600  |
| Spry Painting                 |                 | <del>1000</del> | 600. |
| Wiring.                       |                 | <del>50</del>   | 30   |
| To remove reverse sensor      |                 | <del>100</del>  | 50.  |
| To remove upholstery.         |                 | <del>150</del>  | 40.  |
| To transfer bootlid fittings. |                 | 150             | X    |

SCV 3338E .

To apply tuff coat.

~~150~~ 40.  
1360

total: 2763.50

L/s : 2.2K.

04 Days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: