

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008766/TVCE2**Date:** 23/11/2022REFERENCE

Insured/Claimant:	YEO KOK PENG SEBASTIAN	Policy No:	7210060229-01	
Date of Loss:	31/08/2022	Nature of Claim:	OD	Claim No: 5395767950SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA3160E		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC40418
Reg. Date:	16/06/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF32M1119698
Colour:	Blue	Odometer:	31276 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R19	Rear Tyre Size:	255/45 R19
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,432.00	3,405.28	6,026.72	63.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,472.00	2,592.00	3,880.00	59.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,904.00	5,997.28	9,906.72	62.29
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	15,104.00	5,197.28	9,906.72	65.59
+ GST 7.00/7.00% (S\$)	1,057.28	363.81	693.47	65.59
Nett Amount (S\$)	16,161.28	5,561.09	10,600.19	65.59

INSPECTION

Date of Assignment:	07/09/2022	
Date Inspected:	06/09/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Bent	3,028.00 FS	*2,422.40 FS
2	1		*REAR OUTER DOOR SEAL - LH	Necessary	151.00 FS	*120.40 FS
3	1		*REAR DOOR CATCH - LH	Bent	134.00 FS	*106.80 FS
4	1		*REAR INNER DOOR SEAL - LH	Not Necessary	213.00 FS	*- FS
5	1		*REAR DOOR SILL PANEL - LH	Not Necessary	151.00 FS	*- FS
6	1		*REAR WINDOW WITHOUT REGULATOR MOTOR - LH	Not Necessary	302.00 FS	*- FS
7	1		*REAR WINDOW REGULATOR MOTOR - LH	Not Necessary	300.00 FS	*- FS
8	1		*REAR DOOR CONTROL UNIT - LH	Not Necessary	464.00 FS	*- FS
9	1		*REAR DOOR COVER - LH	Distorted	368.00 FS	*294.00 FS
10	1		*REAR DOOR PANEL - LH	Not Necessary	2,659.00 FS	*- FS
11	1		*REAR WHEEL COVER - LH	Missing	566.00 FS	*452.40 FS
12	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	262.00 FS	*- FS
13	1		*REAR WHEEL SPOILER - LH	Not Necessary	44.00 FS	*- FS
14	1		*FRONT DOOR COVER - LH	Not Necessary	390.00 FS	*- FS
15	1		*SUNDRIES	Necessary	400.00 FS	*9.28 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					9,432.00	3,405.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	400.00
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	0.00
3	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY LHS REAR DOOR, LHS FRONT DOOR, LHS REAR FENDER, 2 DOOR COVERS AND LHS REAR WHEEL ARCH TRIM	New	4,000.00	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,472.00	2,592.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >