

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008771/KVY3Q2**Date:** 30/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00207942101

**Claimant Vehicle No :** SKZ8420B **Insured Vehicle No :** SMF7460Z

Date of Loss: 02/09/2022 Nature of Claim: TP Claim No: SNM22D206284/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SKZ8420B**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4029195

Reg. Date: 04/02/2016 (Man. Year: 2015) Chassis No: RU11109192

Colour: Metallic Maroon Odometer: 176985 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17

Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm

Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,270.00	3,182.12	6,087.88	65.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,410.00	1,530.00	52.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>12,210.00</b>	<b>4,592.12</b>	<b>7,617.88</b>	<b>62.39</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,650.00</b>		
<b>Nett Amount (\$\$)</b>	<b>12,210.00</b>	<b>3,650.00</b>	<b>8,560.00</b>	<b>70.11</b>

**INSPECTION**

Date of Assignment: 06/09/2022

Date Inspected: 06/09/2022 Inspected At: LM AUTO SOLUTION PTE LTD (HQ)  
BLK 10 SIN MING INDUSTRIAL ESTATE  
SECTOR C #01-12  
Singapore 575645

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2022)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKZ8420B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,218.90 FL	*953.00 FL
2	1		*TAIL GATE W/STRIP (\$174.00) (50%)	Distorted / Dented	168.48 FS	*87.00 FS
3	1		*TAIL GATE EMBLEM -VEZEL	Necessary	82.20 FL	*62.00 FL
4	1		*TAIL GATE GLASS MOULDING	Necessary	245.70 FL	*110.20 FL
5	1		*TAIL GATE LOCK	Dented	346.70 FL	*216.00 FL
6	2		*TAIL GATE HINGE LH +RH	Repair	126.00 FL	*- FL
7	1		*TAIL GATE INNER TRIM	Mtg Cracked	486.70 FL	*289.00 FL
8	1		*TAIL GATE W/STRIP	Repeated	211.30 FL	*- FL
9	2		*TAIL GATE LAMP LH+RH	Serviceable	968.00 FL	*- FL
10	2		*TAIL LAMP LH+RH	Serviceable	1,084.00 FL	*- FL
11	1		*REAR BUMPER	Bent	792.60 FL	*762.70 FL
12	2		*REAR BUMPER RETAINER LH+RH	Serviceable	160.00 FL	*- FL
13	2		*REAR BUMPER BRACKET RH+LH	Serviceable	140.00 FL	*- FL
14	2		*REAR BUMPER REFLECTOR LH+RH	Serviceable	328.40 FL	*- FL
15	1		*REAR BUMPER SIDE LH +RH	N/S Cracked	568.80 FL	*195.00 FL
16	1		*SET REAR BUMPER CLIP	Necessary	60.00 FL	*60.00 FL
17	1		*REAR BUMPER UNDER COVER	Serviceable	324.70 FL	*- FL
18	1		*SET REAR BUMPER UNDER COVER CLIP	Not Necessary	60.00 FL	*- FL
19	2		*REAR FENDER INNER TRIM LH+RH	Serviceable	971.20 FL	*- FL
20	1		*REAR END PANEL	Bent	525.60 FL	*517.30 FL
21	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	198.00 FL	*102.00 FL
22	1		*REAR END PANEL SENSOR -KEY	Serviceable	154.30 FL	*- FL
23	1		*SPARE WHEEL PANEL	Repair	682.80 FL	*- FL
24	1		*SPARE WHEEL PANEL TOP BOARD	Serviceable	492.00 FL	*- FL
25	1		*SPARE WHEEL PANEL SPONGE COMPARTMENT	Cracked	324.00 FL	*264.20 FL
26	1		*TAIL GATE W/S GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
27	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
28	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
29	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	60.00 FS	*- FS
30	1		*SPARE WHEEL PANEL INSULATOR	Not Necessary	150.00 FS	*- FS
31	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,380.38</b>	<b>3,888.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,110.38	706.28
<b>Total Parts (\$\$)</b>	<b>9,270.00</b>	<b>3,182.12</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK ,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,000.00	480.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	60.00
4	TO R&R TAIL GATE MECHANISM	New	120.00	60.00
5	TO R&R TAIL GATE W/S GLASS	New	100.00	100.00
6	TO R&R REAR COMPARTMENT ,UPHOLSTERY AND ATTACHMENT PARTS	New	280.00	60.00
7	TO R&R REVERSE CAMERA ,REVERSE SENSOR AND CHECK WIRING	New	120.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,940.00</b>	<b>1,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >