11/24/22, 10:59 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

CS/CTI22008776/EVY3Q2 Our File No:

24/11/2022 Date:

Odometer:

**REFERENCE** 

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMB1SNW00002292200

**Claimant Vehicle** 

PC9729S

Insured Vehicle PZ3888J

No:

Date of Loss: 26/08/2022 Nature of Claim: TP Claim

SNM22D206094/C02/LEEPG

74153 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

PC9729S Reg No:

TOYOTA HIACE, 3.0 COMMUTER GL (A) Make & Model: Engine No: 1KD2777537 Reg. Date: 17/12/2018 (Man. Year: 2017) Chassis No: KDH2230035179

Colour: Silver

**Engine Capacity:** 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 185 R15C Rear Tyre Size: 185 R15C

Front Left Side: Rear Left Side: Bridgestone 4 mm Bridgestone 4 mm Bridgestone 4 mm Front Right Side: Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,642.50	7,522.17	2,120.33	21.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	2,670.00	430.00	13.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,742.50	10,192.17	2,550.33	20.01
+ GST 7.00/7.00% (S\$)	891.98	713.45	178.53	20.02
Nett Amount (S\$)	13,634.48	10,905.62	2,728.86	20.01

**INSPECTION** 

Date of Assignment: 08/09/2022

8 Tuas Avenue 18 Singapore 638892 Date Inspected: 08/09/2022 Inspected At: Repairer: Goldbell Engineering Pte Ltd (Tuas)

Estimated Period of Repair: 10.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$10,192.18

### **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 24 Nov 2022)

Parts: N/A TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC9729S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Dented	1,640.40 FL	*1,640.40 FL
2	1		*TAILGATE	Dented	2,164.80 FL	*1,855.00 FL
3	1		*REAR WINDSCREEN	Broken	1,466.30 FL	*1,254.00 FL
4	1		*SMALL CENTER GLASS	Broken	883.50 FL	*883.50 FL
5	1		*REAR FENDER GLASS	Broken	1,350.90 FL	*1,350.90 FL
6	1		*COMPANY STICKER	Necessary	800.00 FS	*600.00 FS
7	1		*REAR WINDSCREEN SEALANT	Necessary	160.00 FS	*120.00 FS
8	1		*SIDE PANEL SMALL	Dented	1,419.10 FL	*1,419.10 FL
9	1		*SIDE GUARD	Bent	400.00 FS	*300.00 FS
10	1		*REPAIR SIDE SEAT CUSHION	Torn	250.00 FS	*200.00 FS
F=Fra	inchise	part. S=SpcNe	tt. L=ListItemDisc.	Sub Total (S\$)	10,535.00	9,622.90
			- List Item Discount on L	. Items 10.00/25.00% (S\$)	892.50	2,100.73
				Total Parts (S\$)	9,642.50	7,522.17
			Report was unsubmitted	d during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
2	TO REMOVE AND REFIX DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT,STRAIGHTEN & REALIGN ETC	New	1,800.00	1,600.00
3	TO PUTTY ,CLEAN ,SPRAY PAINT AND POLISH ETC	New	1,000.00	800.00
4	REMOVE AND REFIX SIDE FENDER GLASS	New	150.00	150.00
	Gross Lal	oour Cost (S\$)	3,100.00	2,670.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >