

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R							
Affiliated to Federation Internationale Des Experts En Automobile								
	ALLIED WORLD A	SSURANCE COMPANY LTD	Ref:	CS/AWA22008778/Ecy3e2				
	(SINGAPORE BRA 60 ANSON ROAD MAPLETREE ANS SINGAPORE 0799	#08-01 (8th FLOOR) ON	Date:	24/03/2023				
			Code:	AWA				
1.	. Policy Particulars :- OWN DAMAGE							
	Insured Veh.	XE 6903U	Veh. Inspected	TRUCK				
	Policy No.	BVFCSB0007172215	Coverage (\$)	0.00				
	Claim No.	NSV2200131/PC	Excess (\$)	2,500.00				
	Assign From	GOH STELLA	Assign Date	06/09/2022				
2.	. Vehicle Particulars & Condition							
	Make & Model	SCANIA P370	c.c	12742				
	Engine No.	HIDDEN	Year of Reg.	2021				
	Chassis No.	YS2P6X40005634294	Colour	BLUE				
	Odometer	10210 KM	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM				
	General	GOOD						
3.	3. Conditions of Tyres							
		Size	Make	Balance				
	R/H Front Tyre	295/80 R22.5	GOODYEAR	5 mm				
	L/H Front Tyre	295/80 R22.5	GOODYEAR	5 mm				
	R/H Rear Tyre	295/80 R22.5	GOODYEAR	5 mm				
	L/H Rear Tyre	295/80 R22.5	GOODYEAR	5 mm				
4.	_	Description of Damages						
	THE VEHICLE SU	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.						
	DAMAGES SEE D	DAMAGES SEE DETAILS.						
5.								
	Accident Date	22/08/2022	Inspection Date	13/09/2022				
	Survey held at	24 JALAN BUROH S 619480						
	Repairer	PUBLIC TRAILER EQUIPMENT SUPPLIES P/L						
5a.		Remarks						
	A)THE MARKET VALUE IS S\$183,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.							
5b.	Estimate Days of Repair							

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



**LESS EXCESS** 

**NETT LIABILITY** 

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

-2,500.00

2,300.00

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 6903U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	LABOUR, EQUIPMT & MATERIALS - TO REPAIR REAR UNDERCARRIAGE AS PER SCOPE STATED BELOW.		4,800.00	4,800.00
	SCOPE OF WORKS: -CHASSIS ALIGNMENT CHECK -LED TAIL LAMPS AND BRACKETS -REAR UNDERRUN BUMPER AND SUPPORT BRACKETS -REAR SS FLIP-DOWN STEPS -NUMBER PLATE -REVERSE SENSORS AND BRACKETS EXCLUDE ANY OTHER PARTS OF FIXTURES UNLESS OTHERWISE STATED.			
			4,800.00	4,800.00
	GRAND TOTAL		4,800.00	4,800.00
	RECOMMENDED COST OF REPAIRS (TRUCK)			4,800.00

Report Ref No. CS/AWA22008778/Ecy3e2



**Automotive Assessor** 

X:2.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.