1/16/23, 11:28 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS22008782/APA3Q2

16/01/2023 Date:

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

Claimant Vehicle PC7269R Insured Vehicle No: SKA1510C No:

Date of Loss: 04/09/2022 Nature of Claim: TP Claim No: 2022 22006530KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC7269R

Make & Model: TOYOTA HIACE, 2.8 D GL (A) 1GD8298421 Engine No: Reg. Date: 21/08/2018 (Man. Year: 2018) Chassis No: GDH2111001620 Colour: Odometer: 233450 km White

Engine Capacity: 2754 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

195 R15C Front Tyre Size: 195 R15C Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|----------------------------------|------------------------|------------|------------|--------|
| Parts | 3,736.92 | 1,713.75 | 2,023.17 | 54.14 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,550.00 | 930.00 | 620.00 | 40.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$ | 5,286.92 | 2,643.75 | 2,643.17 | 49.99 |
| Approved Total (Overridden) (S\$ | 5) | 2,100.00 | | |
| (\$\$ | 5,286.92 | 2,100.00 | 3,186.92 | 60.28 |
| + GST 7.00/7.00% (S\$ | 370.08 | 147.00 | 223.08 | 60.28 |
| Nett Amount (S\$ | 5,657.00 | 2,247.00 | 3,410.00 | 60.28 |
| + Loss of Use (3.0 | x S\$100.00/day) (S\$) | 300.00 | | |
| +1 | Doc/Search Fee (S\$) | 2.00 | | |
| | Nett Liability (S\$) | 2,549.00 | | |

INSPECTION

Date of Assignment: 06/09/2022

Modern Automotive Pte Ltd (HQ) Date Inspected: 10/10/2022 Inspected At:

Blk 3023A Ubi Road 1, #01-61 & #01-58

Singapore 408717

Estimated Period of Repair: 3.0 days

ADRIAN LING **CHEW HSIAO TONG** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

Reference

1/16/23, 11:28 AM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jan 2023)

Parts: 213 TOYOTA HIACE 2.8 D GL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC7269R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|--|--------------|-------------------------------|-------------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 673.20 FL | *673.20 FL |
| 2 | 1 | | *FRONT BUMPER SIDE HOLDER -LH | Not Necessary | 85.40 FL | *- FL |
| 3 | 1 | | *HEADLAMP -LH | Not Necessary | 2,326.70 FL | *- FL |
| 4 | 1 | | *FRONT DOOR -LH | Dented | 1,571.80 FL | *1,571.80 FL |
| 5 | 1 | | *STEP PANEL GARNISH -LH | Not Necessary | 258.80 FL | *- FL |
| 6 | 1 | | *SET FRONT BUMPER CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 7 | 1 | | *SET STEP PANEL GARNISH CLIPS | Not Necessary | 20.00 FS | *-FS |
| F=Fra | anchise | part. S=SpcN | ett. L=ListItemDisc. | Sub Total (S\$) | 4,965.90 | 2,275.00 |
| | - List Item Discount on L Items 25.00/25.00% (S\$) | | | 1,228.98 | 561.25 | |
| | | | | Total Parts (S\$) | 3,736.92 | 1,713.75 |
| | | | | | | |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|------------------------|------------|--------|
| Lab | <u>our Items</u> | | | |
| 1 | TO KNOCKING & PULL OUT FRONT PORTION & RENEW PA | ARTS New | 600.00 | 400.00 |
| 2 | TO PUTTY & SPRAY UP PAINT WORKS | New | 600.00 | 400.00 |
| 3 | TO CHECK WIRING | New | 50.00 | 30.00 |
| 4 | TO SPRAY TUFF COAT | New | 150.00 | 20.00 |
| 5 | TO TRANSFER DOOR FITTINGS | New | 150.00 | 80.00 |
| | Gr | ross Labour Cost (S\$) | 1,550.00 | 930.00 |
| | Report was unsubmitted | during this print-out | | |

< END OF ESTIMATES >