

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22008783/RPA3Q2**Date:** 20/07/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0000974
Claimant Vehicle No :	SLH4087P	Insured Vehicle No :	SLM3518T
Date of Loss:	02/09/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0005041

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH4087P		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZR581847
Reg. Date:	02/11/2016 (Man. Year: 2016)	Chassis No:	MR053REH104553141
Colour:	Grey	Odometer:	0 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,289.60	5,309.30	1,980.30	27.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,902.40	8,132.40	1,770.00	17.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,192.00	13,441.70	3,750.30	21.81
+ GST 7.00/7.00% (S\$)	1,203.44	940.92	262.52	21.81
Nett Amount (S\$)	18,395.44	14,382.62	4,012.82	21.81
+ Loss of Use (11.0 x S\$60.00/day) (S\$)		660.00		
Nett Liability (S\$)		15,042.62		

INSPECTION

Date of Assignment:	07/09/2022	
Date Inspected:	07/09/2022	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH4087P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
2	1		*REGN PLATE	Not Necessary	80.00 FS	*- FS
3	1		*GREY METALLIC 2 REVERSE SENSOR	Not Working	158.30 FS	*251.40 FS
4	1		*COVER ,RR BUMPER	Deformed	602.60 FS	*602.60 FS
5	10		*PIECE ,RR BUMPER	Necessary	45.00 FS	*45.00 FS
6	1		*REINFORCEMENT SUB-AS	Bent	432.50 FS	*432.50 FS
7	1		*ARM ,RR BUMPER ,OUTE	Not Necessary	73.70 FS	*- FS
8	1		*ARM ,RR BUMPER OUTE	Not Necessary	73.70 FS	*- FS
9	1		*RETAINER ,RR BUMPER	Necessary	118.70 FS	*118.70 FS
10	1		*RETAINER ,RR BUMPER	Necessary	65.60 FS	*65.60 FS
11	1		*RETAINER ,RR BUMPER	Necessary	118.70 FS	*118.70 FS
12	1		*RETAINER ,RR BUMPER	Necessary	65.60 FS	*65.60 FS
13	1		*PANEL SUB-ASSY BODY	Bent	727.70 FS	*727.70 FS
14	1		*PANEL SUB-ASSY LUGG	Bent	852.90 FS	*852.90 FS
15	1		*WEATHERSTRIP ,LUGGAG	Not Necessary	190.10 FS	*- FS
16	2		*ARM SUB-ASSY ,LUG CO	Not Necessary	151.20 FS	*- FS
17	1		*LOCK ASSY ,LUGGAGE C	Bent	432.50 FS	*432.50 FS
18	1		*PLATE ,RR FLOOR FINI	Deformed	261.60 FS	*261.60 FS
19	2		*CLIP	Necessary	6.00 FS	*6.00 FS
20	1		*COVER ,SPARE WHEEL	Cracked	288.40 FS	*288.40 FS
21	1		*EMBLEM ,LUGGAGE COMP	Necessary	66.90 FS	*66.90 FS
22	1		*PLATE ,LUGGAGE COMPT	Necessary	44.40 FS	*44.40 FS
23	1		*PLATE ,LUGGAGE COMPT	Necessary	49.40 FS	*49.40 FS
24	1		*GARNISH SUB-ASSY ,BA	Not Necessary	263.40 FS	*- FS
25	1		*LAMP ASSY ,RR COMBIN	Cracked	410.80 FS	*410.80 FS
26	1		*LAMP ASSY ,RR COMBIN	Cracked	410.80 FS	*410.80 FS
27	2		*GUIDE ,RR	Necessary	7.80 FS	*7.80 FS
28	1		*LAMP ASSY ,RR ,RH	Not Necessary	426.60 FS	*- FS
29	1		*LAMP ASSY ,RR ,LH	Not Necessary	426.60 FS	*- FS
30	1		*REFLECTOR ASSY REFL	Not Necessary	65.00 FS	*- FS
31	1		*REFLECTOR ASSY REFL	Not Necessary	65.00 FS	*- FS
32	1		*ANTENNA ,ELECTRICAL	Not Necessary	208.10 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	7,289.60	5,309.30
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY SEALANT	New	300.00	200.00
2	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
3	CHECK WIRING AND CONDUCT WATER TEST	New	122.40	122.40
4	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	New	720.00	360.00
5	REMOVE AND TRANSFER BOOT LID COMPONENTS ONTO NEW BOOTLID .R/I REAR REVERSE CAMERA TO FAC REPAIR	New	540.00	540.00
6	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
7	REPLACE ACC DAMAGED PARTS	New	4,320.00	3,600.00
8	RESPRAY ACC AFFECTED AREAS	New	3,540.00	2,950.00
Gross Labour Cost (\$\$)			9,902.40	8,132.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >