

## Vehicle Damage Assessment Report for [SLH4087P]

Estimate Created: 07/09/2022 04:16 by LKK\_admin-a  
(LKK\_Auto\_Consultants\_Pte\_Ltd)

Owned: 18/01/2023 16:49 by LKK\_cs-a (LKK\_Auto\_Consultants\_Pte\_Ltd)

### General Information

|                   |                              |                  |
|-------------------|------------------------------|------------------|
| Insurance Company | III                          | Claim Number     |
| Claim Type        | TP                           |                  |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |

### Vehicle Information

|                      |          |                    |         |
|----------------------|----------|--------------------|---------|
| Brand                | Toyota   | Model              | Corolla |
| Engine Type          |          |                    |         |
| License Plate Number | SLH4087P | VIN (or Chassis #) |         |

### Vehicle Condition

|                 |                 |         |
|-----------------|-----------------|---------|
| Damaged Diagram | Odometer        | 0.00 Km |
|                 | Tyres Condition |         |
|                 | Front Left      | mm      |
|                 | Front Right     | mm      |
|                 | Rear Left       | mm      |
|                 | Rear Right      | mm      |

### Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$12,657.80 with 9 days for repair

Insurlogic 5 (18/01/2023 16:47)

**Parts**

| Description               | Number/Type | Qty | Cost   | Markup/Disc.% | Sum    |
|---------------------------|-------------|-----|--------|---------------|--------|
| COVER RR BUMPER           |             | 1   | 602.60 | 0.00 %        | 602.60 |
| PIECE RR BUMPER           |             | 1   | 45.00  | 0.00 %        | 45.00  |
| REINFORCEMENT<br>SUB ASSY |             | 1   | 432.50 | 0.00 %        | 432.50 |
| RETAINER RR<br>BUMPER     |             | 1   | 118.70 | 0.00 %        | 118.70 |
| RETAINER RR<br>BUMPER     |             | 1   | 65.60  | 0.00 %        | 65.60  |
| RETAINER RR<br>BUMPER     |             | 1   | 118.70 | 0.00 %        | 118.70 |
| RETAINER RR<br>BUMPER     |             | 1   | 65.60  | 0.00 %        | 65.60  |
| PANEL SUB ASSY<br>BODY    |             | 1   | 727.70 | 0.00 %        | 727.70 |
| PANEL SUB ASSY<br>LUGG    |             | 1   | 852.90 | 0.00 %        | 852.90 |
| PLATE RR FLOOR            |             | 1   | 261.60 | 0.00 %        | 261.60 |
| CLIP                      |             | 1   | 6.00   | 0.00 %        | 6.00   |
| COVER SPARE WHEEL         |             | 1   | 288.40 | 0.00 %        | 288.40 |
| EMBLEM LUGG COMP          |             | 1   | 66.90  | 0.00 %        | 66.90  |
| PLATE LUGG<br>COMPARTMENT |             | 1   | 44.40  | 0.00 %        | 44.40  |
| PLATE LUGG COMP           |             | 1   | 49.40  | 0.00 %        | 49.40  |
| LAMP ASSY RR<br>COMBI     |             | 1   | 410.80 | 0.00 %        | 410.80 |
| LAMP ASSY RR<br>COMBI     |             | 1   | 410.80 | 0.00 %        | 410.80 |
| GUIDE RR                  |             | 1   | 7.80   | 0.00 %        | 7.80   |

Parts Subtotal 4,575.40

**Labor****Replace/RnR**

| Description                                          | Type | Cost    | Markup/Disc % | Price    |
|------------------------------------------------------|------|---------|---------------|----------|
| SUNDRIES                                             | RnR  | 50.00   | 0.00 %        | 50.00    |
| SEALANT                                              | RnR  | 200.00  | 0.00 %        | 200.00   |
| RNR REVERSE SENSOR                                   | RnR  | 180.00  | 0.00 %        | 180.00   |
| CHECK WIRING                                         | RnR  | 122.40  | 0.00 %        | 122.40   |
| RNR INTERIOR UPHOLSTRY                               | RnR  | 360.00  | 0.00 %        | 360.00   |
| TRANSFER BOOTLID COMPONENT                           | RnR  | 540.00  | 0.00 %        | 540.00   |
| RESET ECU                                            | RnR  | 180.00  | 0.00 %        | 180.00   |
| REPLACE/ REPAIR ACCIDENT AFFECTED<br>ITEMS AND AREAS | RnR  | 3600.00 | 0.00 %        | 3,600.00 |

Paint

| Description                      | Paint Type    | Cost    | Markup/Disc %          | Price    |
|----------------------------------|---------------|---------|------------------------|----------|
| PAINT ON ACCIDENT AFFECTED AREAS | Full spray    | 2850.00 | 0.00 %                 | 2,850.00 |
| Labor Rate                       | S\$ 50 / Hour |         |                        |          |
|                                  |               |         | General Labor Subtotal | 5,232.40 |
|                                  |               |         | Paint Labor Subtotal   | 2,850.00 |
|                                  |               |         | Labor Subtotal         | 8,082.40 |

Summary

|                |           |
|----------------|-----------|
| Repair Cost    | 12,657.80 |
| Discount(0 %)  | (0.00)    |
|                | 12,657.80 |
| Excess         | (0.00)    |
| GST(0.00 %)    | 0.00      |
| Grand Subtotal | 12,657.80 |