



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 1711D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
2	RUBBER MOUNTING (SN)	NOT NECESSARY	36.30	-
1	REAR SILENCER (SN)	NOT NECESSARY	1,030.30	-
1	TAILPIPE TRIM CHROME (SN)	NOT NECESSARY	119.60	-
2	HOLDER EXHAUST SYSTEM (SN)	NOT NECESSARY	124.20	-
1	TRUNK LID (SN)	DENTED	1,257.95	1,257.95
1	TAIL PANEL (SN)	NOT NECESSARY	390.35	-
1	REAR BUMPER PANEL PRIMED (PDC) (SN)	DENTED	1,050.55	1,050.55
1	REAR BUMPER CARRIER (SN)	BENT	490.70	490.70
1	SUPPORT (SN)	BROKEN	47.00	47.00
1	LH ADDITIONAL TURN INDICATOR LAMP (SN)	NOT NECESSARY	64.10	-
1	RH ADDITIONAL TURN INDICATOR LAMP (SN)	NOT NECESSARY	64.10	-
10	BUMP STOP (SN)	NOT NECESSARY	33.00	-
1	REAR FLAP TOWING EYE PRIMED (SN)	NOT NECESSARY	43.95	-
1	REAR FLAP TOWING EYE PRIMED (SN)	NOT NECESSARY	43.95	-
1	REAR WINDOW ESG (SN)	NOT NECESSARY	630.20	-
1	TRUNK LID SEALING (SN)	NOT NECESSARY	97.85	-
1	RR LH LIGHT IN THE TRUNK LID (SN)	NOT NECESSARY	267.40	-
1	RR RH LIGHT IN THE TRUNK LID (SN)	NOT NECESSARY	267.40	-
1	(DG) CLEANER R1 (100ML) (SN)	NOT NECESSARY	26.15	-
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (SN)	NOT NECESSARY	263.10	-
3	BLIND RIVET NUT M6 (SN) (ADDITIONAL)	NECESSARY	8.10	8.10
2	EXPANDING NUT (SN) (ADDITIONAL)	NECESSARY	2.00	2.00
1	RR BUMPER LH INNER SIDE GUIDE (SN) (ADDITIONAL)	BROKEN	163.55	163.55
1	RR BUMPER RH INNER SIDE GUIDE (SN) (ADDITIONAL)	BROKEN	163.55	163.55
7	PLUG BLACK D=5MM (SN) (ADDITIONAL)	NECESSARY	6.65	6.65
			6,842.00	3,340.05
	<u>LABOUR</u>			
	TO REPLACE TAILGATE ,REAR BUMPER CARRIER ,REAR BUMPER AND TAIL PANEL.		4,675.00	1,700.00
	TO RESPRAY TAILGATE AND REAR BUMPER .		2,076.00	1,972.00

Report Ref No. CS/FCI22008787/Eny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	112.00
	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION .		177.00	168.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION .		531.00	504.00
	TO CHECK ELECTRICAL.		177.00	168.00
	TO REPLACE REAR WINDSCREEN GLASS .		574.00	545.00
	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.	NOT NECESSARY	531.00	-
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECK FOR LEAK.	NOT NECESSARY	531.00	-
	TO CONDUCT WATER LEAK TESTS.		75.00	71.00
	TO CARRY OUT BODY CAVITY PRESERVATION.(FOR CUT PANEL).	NOT NECESSARY	531.00	-
			9,996.00	5,240.00
GRAND TOTAL			16,838.00	8,580.05

RECOMMENDED COST OF REPAIRS			8,580.05
------------------------------------	--	--	-----------------

Report Ref No. CS/FCI22008787/Eny3q2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.