

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008791/UVY3Q2**Date:** 07/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00019042201		
Claimant Vehicle No :	SKL1318J	Insured Vehicle No :	GBE8659Y		
Date of Loss:	05/09/2022	Nature of Claim:	TP	Claim No:	SNM22D206329/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL1318J		Engine No:	3A92UDP3000
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)		Chassis No:	MMBSTA13AHH003886
Reg. Date:	20/12/2016 (Man. Year: 2016)		Odometer:	65371 km
Colour:	Grey			
Engine Capacity:	1193 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,696.70	1,843.20	4,853.50	72.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	730.00	2,930.00	80.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,356.70	2,573.20	7,783.50	75.15
Approved Total (Overridden) (\$\$)		2,000.00		
Nett Amount (\$\$)	10,356.70	2,000.00	8,356.70	80.69

INSPECTION

Date of Assignment:	07/09/2022		
Date Inspected:	07/09/2022	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2022)
Parts:	143	mitsubishi attrage 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL1318J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	Scratched	1,051.00 FL	*663.00 FL
2	1		*FRONT BUMPER	Deep Cut	825.00 FL	*703.00 FL
3	1		*FRONT BUMPER CHROME MOULDING (N/S)	Scratched	476.00 FL	*168.00 FL
4	1		*FRONT BUMPER FOG LAMP	Not Necessary	486.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	88.00 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER (N/S)	Bent	28.00 FL	*28.00 FL
7	1		*FRONT FENDER -LH	Bent / Warped	491.00 FL	*428.00 FL
8	1		*FRONT FENDER EMBLEM	Necessary	58.00 FL	*58.00 FL
9	1		*FRONT FENDER INNER SHIELD	Not Necessary	98.00 FL	*- FL
10	1		*FRONT WHEEL HUB	Not Necessary	164.00 FL	*- FL
11	1		*FRONT WHEEL BEARING	Not Necessary	128.00 FL	*- FL
12	1		*FRONT SHOCK ABSORBER	Not Necessary	383.00 FL	*- FL
13	1		*FRONT KNUCKLE ARM	Not Necessary	284.00 FL	*- FL
14	1		*FRONT LOWER ARM	Not Necessary	268.00 FL	*- FL
15	1		*FRONT DRIVE SHAFT -LH	Not Necessary	1,185.00 FL	*- FL
16	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	35.00 FS	*- FS
17	1		*FRONT TYRE	Serviceable	400.00 FS	*- FS
18	1		*FRONT WHEEL RIM -LH	Not Necessary	850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,298.00	2,048.00
- List Item Discount on L Items 10.00/10.00% (S\$)	601.30	204.80
Total Parts (S\$)	6,696.70	1,843.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	350.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	180.00	0.00
4	TO APPLY UNDERCOATING	New	150.00	30.00
5	PANEL BEATING	New	1,500.00	280.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	400.00
Gross Labour Cost (\$)			3,660.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >