

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008793/DQY3M4**Date:** 30/01/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001708063

Claimant Vehicle No : SKR6627C**Insured Vehicle No :** SMY5953G

Date of Loss: 04/09/2022

Nature of Claim: TP

Claim No: 284307

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKR6627C**Make & Model: MAZDA BIANTE, 2.0 BIANTE 5-DOOR WAGON
SP.6E (A)

Engine No: PE30739979

Reg. Date: (Man. Year:)

Chassis No: JM6CC1071F0107231

Colour: Grey

Odometer: 186883 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,561.12	3,770.72	4,790.40	55.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	730.00	1,270.00	63.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,561.12	4,500.72	6,060.40	57.38
Approved Total (Overridden) (\$\$)		3,600.00		
Nett Amount (\$\$)	10,561.12	3,600.00	6,961.12	65.91

INSPECTION

Date of Assignment: 07/09/2022

Date Inspected: 07/09/2022 Inspected At:

Bethlehem Auto (HQ)

Blk 5035 Ang Mo Kio Industrial Park 2, #01-371

Singapore 569538

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2023)
Parts:	M1-MPV	MAZDA BIANTE 2.0 BIANTE 5-DOOR WAGON SP.6E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR6627C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP LH	Mtg Broken	3,690.21 FL	*2,744.40 FL
2	1		*HEAD LAMP LOWER BRACKET LH	Cracked	203.60 FL	*168.10 FL
3	1		*FRONT BUMPER	Dented/Mtg Broken	1,292.32 FL	*1,074.30 FL
4	2		*FRONT BUMPER SIDE RETAINER @\$135.00	Not Necessary	270.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP LH	Mtg Broken	473.21 FL	*329.00 FL
6	1		*FRONT BUMPER FOG LAMP GARNISH LH	Cracked	381.11 FL	*179.00 FL
7	1		*FRONT BUMPER SPONGE	Not Necessary	152.90 FL	*- FL
8	1		*FRONT REINFORCEMENT BAR	Not Necessary	755.20 FL	*- FL
9	1		*FRONT SUPPORT PANEL	Not Necessary	1,860.30 FL	*- FL
10	1		*FRONT FENDER LH	Not Necessary	1,052.20 FL	*- FL
11	1		*FRONT FENDER INNER SHIELD LH	Torn	264.10 FL	*181.10 FL
12	1		*SET NO. PLATE & GARNISH	Not Necessary	80.00 FS	*- FS
13	1		*SET FRONT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
14	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*15.00 FS
15	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
16	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,640.15	4,705.90
- List Item Discount on L Items 20.00/20.00% (S\$)	2,079.03	935.18
Total Parts (S\$)	8,561.12	3,770.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	700.00	400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	700.00	300.00
3	TO APPLY TUFF COAT ON ALL AFFECTED AREAS	New	80.00	0.00
4	TO RNR A/C CONDENSOR & RADIATOR TO FACILITATE REPAIRS	New	120.00	0.00
5	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	100.00	30.00
6	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			2,000.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >