



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 7655C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR LH	BENT	1,164.50	1,164.50
1	REAR DOOR PROTECTOR	DENTED	514.50	225.00
1	REAR DOOR OUTER HANDLE	SERVICEABLE	341.60	-
1	REAR DOOR WINDOW REGULATOR	DISTORTED	435.10	218.70
1	REAR DOOR WINDOW REGULATOR MOTOR	JAMMED	514.50	514.50
1	REAR DOOR SLIDE LOWER	SERVICEABLE	116.70	-
1	REAR DOOR SLIDE UPPER	SERVICEABLE	150.60	-
1	REAR DOOR SLIDE RAIL LOWER	SERVICEABLE	245.10	-
1	REAR FENDER	TO REPAIR SEE LABOUR	1,057.40	-
1	REAR FENDER ARCH PROTECTOR	DENTED	245.60	108.60
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,076.40	-
1	REAR BUMPER PROTECTOR TRIM	SERVICEABLE	211.70	-
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	69.50	-
1	REAR WHEEL BEARING ASSY	SERVICEABLE	567.50	-
1	REAR AXLE	SERVICEABLE	1,540.50	-
1	REAR FENDER UPPER TRIM	SERVICEABLE	667.50	-
	LESS 20% DISCOUNT		-1,783.74	-446.26
			7,134.96	1,785.04
<u>SPECIAL NETT ITEMS</u>				
1	ALLOY RIM (SN)	SERVICEABLE	700.00	-
1	REAR SHOCK ABSORBER (SN)	SERVICEABLE	3,645.00	-
			4,345.00	-
<u>LABOUR</u>				
	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE, PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR FENDER AND REAR BUMPER.		800.00	450.00
	TO CHECK WIRING SYSTEM.		80.00	20.00
	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS.		900.00	600.00

Report Ref No. CS/INC22008795/Kqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE UNDERCARRIAGE.	NOT NECESSARY	360.00	-
	TO TRANSFER DOOR ACCESSORIES.		60.00	60.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		150.00	30.00
	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT.		85.00	60.00
			2,585.00	1,220.00
GRAND TOTAL			14,064.96	3,005.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,300.00

Report Ref No. CS/INC22008795/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.