



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 4876E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,264.90	-
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	316.20	-
1	REAR BOOT OUTER GARNISH	SERVICEABLE	564.70	-
1	REAR BOOT EMBLEM "VEZEL"	NOT NECESSARY	67.50	-
1	REAR BOOT EMBLEM "LOGO"	NOT NECESSARY	62.80	-
1	REAR BOOT EMBLEM "HYBRID"	NOT NECESSARY	69.40	-
1	REAR BOOT LOCK CATCH	TO REPAIR SEE LABOUR	48.10	-
1	REAR BUMPER	BUCKLED	895.70	762.70
1	REAR BUMPER SIDE COVER	SERVICEABLE	473.60	-
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	69.80	-
1	REAR BUMPER LOWER DUST COVER	SERVICEABLE	315.60	-
1	REAR WHEEL ARCH PROTECTOR	SERVICEABLE	419.40	-
1	REAR BUMPER REFLECTOR	SERVICEABLE	364.70	-
1	REAR END INNER PANEL	TO REPAIR SEE LABOUR	577.60	-
1	REAR END PANEL GARNISH	SERVICEABLE	473.20	-
1	REMOTE LOCK SENSOR	SERVICEABLE	350.80	-
1	REMOTE LOCK BUZZER	SERVICEABLE	215.40	-
	LESS 20% DISCOUNT		-1,309.88	-152.54
			5,239.52	610.16
<b><u>SPECIAL NETT ITEMS</u></b>				
1	WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
1	REVERSE SENSOR (SN)	SERVICEABLE	400.00	-
			460.00	-
<b><u>LABOUR</u></b>				
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR BOOT LID, REAR BOOT LOCK, REAR BOOT LOCK CATCH AND REAR END INNER PANEL.		1,100.00	200.00

Report Ref No. CS/INC22008798/Kqy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING SYSTEM.	NOT NECESSARY	60.00	-
	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		1,100.00	220.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO APPLY WATER PROOF SEALANT ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO REMOVE REAR WINDSCREEN GLASS TO ENABLE REPAIR.	NOT NECESSARY	140.00	-
			2,650.00	420.00
<b>GRAND TOTAL</b>			<b>8,349.52</b>	<b>1,030.16</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>800.00</b>

Report Ref No. CS/INC22008798/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.