

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008799/DNY3Q2**Date:** 13/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00072642100		
Claimant Vehicle No :	SMR355C	Insured Vehicle No :	GBD9000X		
Date of Loss:	05/09/2022	Nature of Claim:	TP	Claim No:	SNM22D206355/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR355C	Engine No:	LEB1448240
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GP51339760
Reg. Date:	16/12/2019 (Man. Year: 2018)	Odometer:	105220 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,596.56	1,866.12	14,730.44	88.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	1,400.00	4,850.00	77.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,846.56	3,266.12	19,580.44	85.70
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	22,846.56	2,600.00	20,246.56	88.62
+ GST 7.00/7.00% (S\$)	1,599.26	182.00	1,417.26	88.62
Nett Amount (S\$)	24,445.82	2,782.00	21,663.82	88.62

INSPECTION

Date of Assignment:	07/09/2022	JWG International Pte Ltd (HQ)
Date Inspected:	07/09/2022 Inspected At:	Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Estimated Period of Repair:	5.0 days	Singapore 568047

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2023)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR355C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,102.00 FL	*- FL
2	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	201.50 FL	*- FL
3	1		*TAILGATE CENTER GARNISH	Not Necessary	301.20 FL	*- FL
4	1		*TAILGATE HONDA LOGO	Not Necessary	55.00 FL	*- FL
5	1		*TAILGATE HYBRID EMBLEM	Not Necessary	92.00 FL	*- FL
6	2		*TAILGATE DAMPER LH/RH	Not Necessary	645.80 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	429.30 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Necessary	331.20 FL	*148.20 FL
9	1		*SET TAILGATE STOPPERS	Not Necessary	20.00 FL	*- FL
10	1		*TAILGATE LOCK	Not Necessary	342.40 FL	*- FL
11	1		*TAILGATE SWITCH	Not Necessary	442.30 FL	*- FL
12	1		*TAILGATE STRIKER LOCK	Not Necessary	109.30 FL	*- FL
13	1		*TAILGATE INNER HANDLE	Not Necessary	99.80 FL	*- FL
14	2		*TAILGATE NO.PLATE LAMP LH/RH	Not Necessary	190.00 FL	*- FL
15	2		*TAILGATE LAMP LH/RH	Not Necessary	591.60 FL	*- FL
16	2		*TAIL LAMP LH/RH	Not Necessary	984.80 FL	*- FL
17	2		*TAIL LAMP PANEL LH/RH	Not Necessary	803.60 FL	*- FL
18	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	203.60 FL	*- FL
19	1		*REAR BUMPER	Distorted / Mtg Cracked	659.40 FL	*568.30 FL
20	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	133.80 FL	*- FL
21	1		*REAR BUMPER CENTER GARNISH	Mtg Cracked	398.70 FL	*146.90 FL
22	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	219.60 FL	*- FL
23	1		*REAR BUMPER REFLECTOR GARNISH LH/RH	Mtg Cracked	419.60 FL	*150.40 FL
24	1		*REAR BUMPER LOWER LID	Not Necessary	498.50 FL	*- FL
25	1		*REAR END PANEL	Dented	784.50 FL	*468.50 FL
26	1		*REAR END PANEL TOP GARNISH	Deformed / Bent	295.30 FL	*130.20 FL
27	1		*SPARE WHEEL PANEL	Not Necessary	994.80 FL	*- FL
28	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	985.40 FL	*- FL
29	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	599.00 FL	*- FL
30	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	398.00 FL	*- FL
31	2		*REAR FENDER LH/RH	Not Necessary	2,659.40 FL	*- FL
32	2		*REAR FENDER INNER TRIM LH/RH	Not Necessary	985.60 FL	*- FL
33	2		*REAR FENDER AIR DUCT LH/RH	Not Necessary	198.00 FL	*- FL
34	2		*REAR FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	337.60 FL	*- FL
35	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
36	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	50.00 FS	*- FS
37	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*TAILGATE CENTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
40	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
41	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
42	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

1/13/23, 2:38 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR NO PLATE & CASING	Not Necessary	100.00 FS	*- FS
48	1		*REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
49	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
50	2		*REAR BUMPER SPONGE LH/RH	Torn	376.30 FL	*176.20 FL
51	1		*KEYLESS SENSOR	Mtg Cracked	334.30 FL	*95.60 FL
52	1		*BUZZER SENSOR	Mtg Broken	397.50 FL	*92.10 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					20,320.70	2,261.40
- List Item Discount on L Items 20.00/20.00% (\$\$)					3,724.14	395.28
Total Parts (\$\$)					16,596.56	1,866.12
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
7	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	0.00
8	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	100.00	0.00
10	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
11	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	40.00
12	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,250.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >