

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008801/GPA3Q2**Date:** 10/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800077637
Claimant Vehicle No :	SJN193J	Insured Vehicle No :	SMC4445D
Date of Loss:	04/09/2022	Nature of Claim:	TP
		Claim No:	0841358303SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN193J	Engine No:	3ZZ4836911
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106130966
Reg. Date:	23/01/2009 (Man. Year: 2008)	Odometer:	364873 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Matrex 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Matrex 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,345.65	6,192.75	2,152.90	25.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,520.00	1,220.00	44.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,085.65	7,712.75	3,372.90	30.43
Approved Total (Overridden) (S\$)		6,150.00		
Nett Amount (S\$)	11,085.65	6,150.00	4,935.65	44.52
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		38.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		6,668.45		

INSPECTION

Date of Assignment:	05/09/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	05/09/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	490.00 FL	*490.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Deformed	140.00 FL	*140.00 FL
3	1		*FRONT BUMPER LOGO	Necessary	85.00 FL	*85.00 FL
4	1		*FRONT BUMPER FOG LAMP	O/S Cracked	600.00 FL	*300.00 FL
5	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	284.00 FL	*- FL
6	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	170.00 FL	*- FL
7	1		*FRONT BUMPER TOP RUBBER	Cut	75.00 FL	*75.00 FL
8	2		*FRONT BUMPER LOWER COVER GARNISH	Torn	200.00 FL	*200.00 FL
9	2		*FRONT BUMPER SIDE RETAINER	Damaged	150.00 FL	*150.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	380.00 FL	*380.00 FL
11	1		*FRONT RADIATOR GRILLE	Cracked	360.00 FL	*360.00 FL
12	2		*HEADLAMP	Cracked	1,560.00 FL	*1,560.00 FL
13	2		*HEADLAMP LOWER BRACKET	Not Necessary	190.00 FL	*- FL
14	2		*FRONT FENDER INNER COWLING	Torn	340.00 FL	*340.00 FL
15	2		*BONNET STOPPER	Not Necessary	40.00 FL	*- FL
16	1		*BONNET LOCK	Damaged	110.00 FL	*110.00 FL
17	1		*BONNET LOCK BRACE PANEL	Bent	118.00 FL	*118.00 FL
18	1		*FRONT SUPPORT PANEL	Buckled	750.00 FL	*750.00 FL
19	1		*HORN	Not Necessary	130.00 FL	*- FL
20	1		*AIR CONDENSOR	Warpped	1,510.00 FL	*1,289.00 FL
21	1		*AIR CONDENSOR SUPPORT PANEL (TOP)	Repair	111.00 FL	*- FL
22	1		*AIR CONDENSOR SUPPORT PANEL (BOTTOM)	Repair	111.00 FL	*- FL
23	1		*RADIATOR	Damaged	2,030.00 FL	*1,450.00 FL
24	2		*RADIATOR TOP BRACKET	Not Necessary	58.00 FL	*- FL
25	4		*RADIATOR MOUNTING	Necessary	100.00 FL	*100.00 FL
26	1		*WIPER WASHER TANK	Not Necessary	151.10 FL	*- FL
27	1		*TEMPERATURE SENSOR	Not Necessary	191.10 FL	*- FL
28	1		*FRONT NUMBER PLATE (SPECIAL TYPE)	Missing	150.00 FS	*60.00 FS
29	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
30	1		*SET FRONT BUMPER LOWER COVER GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
31	1		*SET ENGINE UNDER COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
32	1		*SET FRONT FENDER COWLING CLIPS	Necessary	60.00 FS	*60.00 FS
33	1		*FRONT SUPPORT PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
34	1		*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,954.20	8,167.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,608.55	1,974.25
Total Parts (\$\$)	8,345.65	6,192.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	600.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
5	REFOCUS HEADLAMP BEAM	New	60.00	0.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (S\$)			2,740.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >