

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	Ref:		CS3/LPC22008802/Gcy3e2		
	300 BEACH ROAD SINGAPORE 1995		Date:	23/09/2022		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YN 3653B	Veh. Inspected		SMP 9794U	
	Policy No.	Coverage (\$)			0.00	
	Claim No.	22/22/22/VC05/026263	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		07/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	KIA CERATO 1.6	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KNAF1416MK5052280	Colour		GREY	
	Odometer	78106 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	NEXEN		6 mm	
	L/H Front Tyre	195/65 R15	NEXEN		6 mm	
	R/H Rear Tyre	195/65 R15	NEXEN		6 mm	
	L/H Rear Tyre	195/65 R15	NEXEN		6 mm	
4. Description of Damages						
		STAINED DAMAGES AT THE REAR PORTION. THE AFFECTED DUE TO COLLISION.				
5.	General Information					
	Accident Date	07/09/2022	Inspect Date /	Time	07/09/2022 (04:30 PM)	
	Survey held at	D'S GRAFFITI CONCEPTS PTE LTD				
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22008802/Gcy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor