

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008804/GYA3Q2**Date:** 19/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900233912
Claimant Vehicle No :	SML1883U	Insured Vehicle No :	SMQ2688J
Date of Loss:	01/09/2022	Nature of Claim:	TP
		Claim No:	3295743840SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML1883U	Engine No:	2ZR0C32640
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800343364
Reg. Date:	08/05/2019 (Man. Year: 2018)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,303.60	4,588.72	6,714.88	59.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,880.00	730.00	27.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,913.60	6,468.72	7,444.88	53.51
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	13,913.60	5,100.00	8,813.60	63.35
+ GST 8.00/8.00% (S\$)	1,113.09	408.00	705.09	63.35
Nett Amount (S\$)	15,026.69	5,508.00	9,518.69	63.35
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,015.45		

INSPECTION

Date of Assignment:	05/09/2022	Green Forest Automobile Pte Ltd (Kaki Bukit)
Date Inspected:	05/09/2022 Inspected At:	8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 415875

Adjuster: XING GUO QIANG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	1,774.20 F	*1,774.20 FL
2	1		*REAR BOOT LID HYBIRD LOGO	Necessary	40.00 F	*40.00 FL
3	1		*REAR BOOT LID LOCK	Cut	385.10 F	*385.10 FL
4	1		*REAR BOOT LID CENTER MOULDING	Not Necessary	315.00 F	*- FL
5	6		*REAR BOOT LID CENTER MOULDING CLIPS	Not Necessary	39.00 F	*- FL
6	1		*REAR BOOT LID WEATHERSTRIP	Twisted	285.00 F	*285.00 FL
7	1		*REAR BOOT LID EMBLE LOGO	Necessary	75.00 F	*75.00 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	117.00 F	*- FL
10	1		*REAR BOOT LID INNER RUBBER	Not Necessary	265.00 F	*- FL
11	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	552.10 F	*552.10 FL
12	1		*REAR WINDSCREEN SEAL	Necessary	215.30 F	*215.30 FL
13	2		*BOOT LID SIDE REFLECTOR	Not Necessary	430.00 F	*- FL
14	1		*REAR BUMPER	Deformed	1,455.00 F	*1,050.00 FL
15	1		*REAR BUMPER TOWING COVER	Not Necessary	68.00 F	*- FL
16	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	170.00 F	*- FL
17	2		*REAR BUMPER SIDE BRACKET	Not Necessary	310.00 F	*- FL
18	2		*REAR BUMPER SIDE RETAINER	Not Necessary	270.00 F	*- FL
19	2		*REAR BUMPER MUD SHIELD	Not Necessary	310.00 F	*- FL
20	8		*REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
21	1		*REAR BUMPER REINFORCEMENT	Not Necessary	658.00 F	*- FL
22	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	350.00 F	*- FL
23	1		*REAR BOOT LID INNER TRIM BOARD HANDLE	Not Necessary	168.00 F	*- FL
24	1		*REAR LOWER BUMPER	Not Necessary	485.00 F	*- FL
25	1		*ANTENNA ELECTRICAL KEY	Damaged	425.00 F	*185.00 FL
26	1		*END PANEL	Dented	783.20 F	*783.20 FL
27	1		*END PANEL TOP GARNISH	Deformed	258.20 F	*258.20 FL
28	1		*REAR SPARE TYRE PANEL TOP SPONGE	Not Necessary	265.30 F	*- FL
29	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	485.20 F	*485.20 FL
30	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	250.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	11,303.60	6,118.30
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,529.58
Total Parts (\$)	11,303.60	4,588.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	60.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	40.00
4	TO REMOVE & REFIX REAR REVERSE SENSOR	New	120.00	0.00
5	TO CHECK WIRING SYSTEM	New	80.00	0.00
6	TUFF KOTE	New	120.00	60.00
7	PANEL BEATING	New	1,000.00	800.00
8	SPRAY PAINTING	New	1,000.00	800.00
Gross Labour Cost (S\$)			2,610.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >