



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 8472G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SIDE MIRROR ASSY	DENTED / CUT	2,155.00	1,180.00
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	2,844.00	-
1	FRONT DOOR W/STRIP RH	SERVICEABLE	263.00	-
1	FRONT DOOR OUTER MOULDING RH	SERVICEABLE	198.00	-
1	FRONT DOOR HANDLE RH	CUT	296.00	296.00
1	FRONT DOOR STICKER RH	NOT NECESSARY	157.00	-
1	REAR DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-591.30	-147.60
			5,321.70	1,328.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET SIDE MIRROR CARBON FIBER GARNISH (SN)	MTG CRACKED	1,200.00	480.00
			1,200.00	480.00
	<b><u>LABOUR</u></b>			
	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH AND REAR DOOR RH.		600.00	200.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		500.00	350.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	30.00	-
	TO R & R FRONT DOOR MECHANISM RH.	NOT NECESSARY	180.00	-
	TO R & R SIDE MIRROR AND RESET SYSTEM.	NOT NECESSARY	100.00	-
			1,410.00	550.00
	<b>GRAND TOTAL</b>		<b>7,931.70</b>	<b>2,358.40</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,850.00</b>

Report Ref No. CS/AGI22008805/Kcy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.