

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNA 1712B Yr Regn: 2021 June
Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mercedes Benz GLA 200 c.c. 1332
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 10661 T/Radio: Insured / Std / NI / NA
Eng/No: W1N 2477872
C/No: J207788
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 235/55R18
R: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

<u>Front</u>		<u>Rear</u>
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. _____		D.O.I. <u>12/9/22 02pm</u>
Survey held at <u>Xinyun</u>		
Des. of Damages : Frt / Rear / O/S / N/S / U/G / Rooftop - or		

Des. of Damages : Frt / Rear / O/S / N/S / U/G / Rooftop- or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Date/Time, File Pass 10?

☐ : Prel. Report

It

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

Site Insp (\$

☐ : Interview (\$

□: Tech. Invs (\$)

Weekend of

Survey Fee:

Transportation:

1) $S + RS \rightarrow SI$

Pholcs

Others

TOTAL

Report Format :

Lump Sum / L.S. / T.)



Xin Yun Auto Private Limited
辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: **SNA1712B**

Model: **MERCEDES GLA200 NEW MODEL**

WIN247

No	Qty	Parts Description	Estimated Parts Price
1	1	Bumper assy ✓	\$ 2,250.00 CRA1354
2	2	Bumper side bracket ✓	\$ 280.00 BT
3	2	Bumper side retainer	\$ 260.00 CUT/CRA182
4	2	△Bumper internal mounting center bracket ✓	\$ 240.00 CRA200
5	2	Bumper lower reflector X	\$ 200.00 NN
6	1	Bumper top silver trim /luggage ✓	\$ 320.00 NEC 250
7	1	Bumper lower trim-bumper diffuser ✓	\$ 350.00 DD
8	1	Reinforcement ✓	\$ 850.00 572DD
9	1	△Reinforcement top cover garnish bracket ✓	\$ 380.00 de ✓
10	2	Tailgate absorber	\$ 1,200.00 X NN
11	1	Emblem	\$ 165.35 NEC 72
12	1	GLA200 logo	\$ 188.35 NEC 105
13	1	Tailgate assy	\$ 2,600.00 BUC 2371
14	1	△Tailgate /front trim cover ✓	\$ 285.00 X NN
15	1	Tailgate lock ✓	\$ 280.00 BT
16	1	Tailgate inner trim whole piece ✓	\$ 295.00 CRA
17	1	Tailgate number plate light ✓	\$ 120.00 X NN
18	1	Tailgate control button X	\$ 200.00 X SVC
19	1	Tailgate rubber garnish	\$ 325.00 DD
20	1 X	Light bracket-left RH CRA	\$ 400.00 200
21	1	Tailight light	\$ 680.00 X NA
22	1	Tailight light ✓ (CRH)	\$ 680.00 579
23	1	△Lower lip silving chrome ✓	\$ 420.00 BB CRA
24	1	△Lower lip base ✓	\$ 680.00 CRA 540
25	2	△Exhaust base ✓	\$ 300.00 CRA
26	2	Exhaust cover silver cover X	\$ 380.00 X NN
27	1	Tow cover	\$ 170.00 X NN
28	2	Rear light support bracket	\$ 250.00 X NN
29	1	Switch sensor with cable	\$ 650.00 X NN
30	1	△Tailgate middle trim	\$ 380.00 X NN
31	1	Wheel arch trim-rear left	\$ 195.00 X NN
36	2	△Wheel arch trim -rear left	\$ 380.00 X NN
37	2	Rear lamp combination	\$ 180.00 X NN
38	1	Exhaust heat shield, need remove exhaust to replace ✓	\$ 300.00 X SVC
39	1	△Sensor cable	\$ 250.00 X SVC
		Parts sub-total	\$ 17,083.00

9055

10% 8149.50



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SNA1712B

Modle: MERCEDES GLA200 NEW MODEL

No	Qty	Parts Description / Special Nett Item	Estimated Parts Price
1	10	Rear bumper clips	\$ 100.00 40 NEC
2	8	Rear end lower panel top garnish clips	\$ 80.00 30 NEC
3	1	Rear end lower panel sealant	\$ 120.00 XNN
4	8	Rear tailgate inner trim board clips	\$ 80.00 30 NEC
5	8	Rear tailgate outer garnish clips	\$ 80.00 30 NEC
6	12	Rear lower lip clips	\$ 100.00 XNN
	10	Bumper diffuser clips	\$ 100.00 XNN
7	1	Tailgate middle trim clips	\$ 120.00 XNN
8	1	Rear windscreen glass sealant -necessary to replace tailgate	\$ 120.00 50 NEC
9	8	Rear windscreen garnish clips -necessary to replace tailgate	\$ 80.00 XNN
10	1	Rear windscreen rubber seal -necessary for replace tailgate	\$ 150.00 40 NEC
11	6	Rear bumper reverse sensor - list item, subject to document	\$ 1,500.00 short 430
12	1	Rear no plate with garnish	\$ 100.00 XNN
13	6	Sensor O-rings	\$ 120.00 90 3 NEC
14	6	Sensor bracket holder (inside bumper -one time only)	\$ 120.00 80 J#EC
Special Nett Items			\$ 2,970.00

820



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SNA1712B

Modle: MERCEDES GLB200

No	Description	Labour Charges	
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00	30
2	Carry up body cavity preservation for affected area \$80 per panel	\$ 320.00	40
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 2,500.00	600
4	Spray painting for accident affected damaged area, including: Tailgate in & out, bumper, rear end panel side cover x2, fender	\$ 2,000.00	500
5	To replacing rear undercarriage parts, including brake bleeding brake system etc.	\$ 120.00	X 111
6	Carry out wheel alignment	\$ 120.00	X 111
7	Removing and installing rear bootlid compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 180.00	60
8	Transferring tailgate /bootlid lock mechanisam, trimming etc to the new tailgate /bootlid	\$ 120.00	60
9	Removing and installing rear exhaust muffler assy to facilitate the repair	\$ 150.00	X
10	Checking central lock system for proper function	\$ 120.00	X
11	Checking auto door system for proper function	\$ 120.00	X
12	Removing and installing rear fender internal garnish and trimming to facilitate the necessary repair	\$ 150.00	X
13	Removing and installing rear window /windscreen glass	\$ 150.00	120
14	To remove and install rear camera	\$ 80.00	30
15	Transferring tailgate and rear end wiring harness for proper function	\$ 150.00	X Rpt
16	Water test after accident repair body work	\$ 120.00	X 111
17	Paint protection coating for accident affected areas	\$ 350.00	X 111
18	Carry out diagnosis check including cleaning accident fault code	\$ 150.00	180
19	Programming coding for accident repair work completed	\$ 600.00	

Total labour : \$ 7,580.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8149.50 1620

820

1620

10589.50

11584.50, 5 days