



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 8768P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (N)	DEFORMED	2,050.00	1,874.00
10	REAR BUMPER CLIPS (N)	NECESSARY	200.00	50.00
1	REAR BUMPER MOULDING (N)	DEFORMED	350.00	350.00
1	REAR BUMPER LOWER PAD (N)	DEFORMED	325.00	325.00
2	REVERSE SENSOR @\$280.00 (N)	NOT NECESSARY	560.00	-
1	REAR BUMPER LAMP (N)	NOT NECESSARY	48.00	-
	LESS 10% DISCOUNT		-353.30	-259.90
			3,179.70	2,339.10
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY.		400.00	250.00
	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION .		480.00	250.00
	TO REMOVE REVERSE SENSOR .		120.00	50.00
	TO CHECK WIRING FUNCTIONS.		100.00	30.00
			1,100.00	580.00
	GRAND TOTAL		4,279.70	2,919.10
RECOMMENDED COST OF REPAIRS				2,919.10

Report Ref No. CS/AGI22008816/Avy3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.