

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008817/GNY3Q2**Date:** 12/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00001272200

**Claimant Vehicle No :** SMZ7402L **Insured Vehicle No :** PC5624L

Date of Loss: 05/09/2022 Nature of Claim: TP Claim No: SNM22D206364/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMZ7402L**

Make & Model: HONDA SHUTTLE, 1.5 G CVT SENSING (A) Engine No: L15B6021566

Reg. Date: 15/05/2021 (Man. Year: 2019) Chassis No: GK82101327

Colour: White Odometer: 46176 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,430.64	3,335.28	1,095.36	24.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,850.00	970.00	34.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,250.64</b>	<b>5,185.28</b>	<b>2,065.36</b>	<b>28.49</b>
<b>+ GST 8.00/8.00% (\$\$)</b>	<b>580.05</b>	<b>414.82</b>	<b>165.23</b>	<b>28.49</b>
<b>Nett Amount (\$\$)</b>	<b>7,830.69</b>	<b>5,600.10</b>	<b>2,230.59</b>	<b>28.49</b>

**INSPECTION**

Date of Assignment: 07/09/2022

Date Inspected: 08/09/2022 Inspected At: Vin's Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive, #03-03, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 6.0 days

**Adjuster:** XING GUO QIANG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount:\$5,185.29

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 12 Jan 2023)	
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 G CVT SENSING (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMZ7402L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Buckled	799.50 FL	*799.50 FL
2	1		*REAR RH DOOR OUTER MOULDING	Not Necessary	53.80 FL	*- FL
3	1		*REAR RH DOOR PILLAR STICKER	Necessary	25.10 FL	*25.10 FL
4	1		*REAR RH DOOR POWER WINDOW MOTOR WITH GEAR	Broken	248.70 FL	*248.70 FL
5	1		*REAR RH FENDER	Buckled	1,010.90 FL	*1,010.90 FL
6	1		*REAR RH FENDER GLASS	Not Necessary	680.30 FL	*- FL
7	1		*RH SIDE SKIRT	Broken	363.20 FL	*363.20 FL
8	1		*REAR RH WHEEL SPORT RIM	Cut	450.40 FL	*450.40 FL
9	1		*REAR RH WHEEL SHOCK ABSORBER	Not Necessary	285.10 FL	*- FL
10	1		*REAR RH WHEEL BEARING	Jammed	321.10 FL	*321.10 FL
11	1		*REAR AXLE	Bent	950.20 FL	*950.20 FL
12	1		*REAR RH WHEEL TYRE	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,468.30</b>	<b>4,169.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,037.66	833.82
<b>Total Parts (\$)</b>	<b>4,430.64</b>	<b>3,335.28</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WHEEL ALIGNMENT	New	150.00	60.00
2	TO REMOVE AND REPLACE REAR RH FENDER GLASS	New	150.00	0.00
3	TO REMOVE AND REFIX ROOF LINING AND SEAT CUSHION	New	380.00	60.00
4	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	280.00	150.00
5	TO REPAIR DAMAGES	New	880.00	700.00
6	TO SPRAY PAINTING	New	980.00	880.00
<b>Gross Labour Cost (S\$)</b>			<b>2,820.00</b>	<b>1,850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >