

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III22008818/UYA3Q2**Date:** 19/05/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MCV0002672\_03

**Claimant Vehicle No :** SMA3200K **Insured Vehicle No :** GBG8947E

Date of Loss: 03/09/2022 Nature of Claim: TP Claim No: MCV2022D0004936

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMA3200K**  
 Make & Model: SUBARU XV, 2.0 I-S EYESIGHT AWD CVT (A) Engine No: FB20YC81975  
 Reg. Date: 02/06/2018 (Man. Year: 2018) Chassis No: JF1GT7KL5JG031710  
 Colour: White Odometer: 92963 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,079.92	724.08	2,355.84	76.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	750.00	270.00	26.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,099.92</b>	<b>1,474.08</b>	<b>2,625.84</b>	<b>64.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>(S\$)</b>	4,099.92	1,150.00	2,949.92	71.95
<b>+ GST 7.00/7.00% (S\$)</b>	286.99	80.50	206.49	71.95
<b>Nett Amount (S\$)</b>	<b>4,386.91</b>	<b>1,230.50</b>	<b>3,156.41</b>	<b>71.95</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,532.50</b>		

**INSPECTION**

Date of Assignment: 09/11/2022

Date Inspected: 09/11/2022 Inspected At:

Hock Wah Motor Workshop Pte Ltd (Bedok)  
 Blk 3011, Bedok Industrial Park E., #01-  
 2008/2010/2012  
 Singapore 489977

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2022)
Parts:	M1-SUV	SUBARU XV 2.0 I-S EYESIGHT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA3200K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Badly Dented	280.00 FL	*280.00 FL
2	1		*FRONT FENDER PROTECTOR LH	Distorted	140.90 FL	*140.90 FL
3	1		*FRONT BUMPER	Cut	468.50 FL	*468.50 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	372.80 FL	*- FL
5	1		*FRONT BUMPER RRETAINER LH	Cracked	15.70 FL	*15.70 FL
6	1		*HEADLAMP LH	Serviceable	2,521.00 FL	*- FL
7	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	51.00 FL	*- FL
					Sub Total (\$\$)	3,849.90 905.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	769.98 181.02
					Total Parts (\$\$)	3,079.92 724.08

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	400.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	500.00	400.00
3	ANTI-RUST COATING	New	80.00	30.00
4	WIRING	New	40.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,020.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >