



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FY 6980D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER SET WITH PETROL TANK	TO REPAIR SEE LABOUR	600.00	-
2	FRONT FORK ASSEMBLY @\$230.00	BENT	460.00	460.00
2	FRONT FORK OIL SEAL @\$95.00	NECESSARY	190.00	125.00
1	HANDLE BAR	BENT	150.00	150.00
4	SIGNAL LIGHT @\$95.00	N/S CRACKED	380.00	68.00
1	STEERING CONE BEARING	NECESSARY	120.00	120.00
1	FRONT STEM SUB ASSY, STEERING	BENT	360.00	260.00
1	METER ASSY COMP	CRACKED	950.00	885.00
2	REAR ABSORBER SHOWA @\$900.00	N/S SCRATCHED	1,800.00	600.00
2	REAR VIEW MIRROR @\$30.00	N/S SCRATCHED	60.00	30.00
1	EXHAUST MUFFLER YOSHIMURA	NOT NECESSARY	950.00	-
1	HEAD LAMP COMP ASSY	CRACKED	450.00	380.00
	LESS 10% DISCOUNT		-	-307.80
			6,470.00	2,770.20
<u>LABOUR</u>				
	BIKE ALIGNMENT.		120.00	50.00
	TOWING SERVICE.	NOT NECESSARY	100.00	-
	LABOUR. INCLUSIVE OF THE REPAIR OF COVER SET WITH PETROL TANK.		400.00	300.00
			620.00	350.00
GRAND TOTAL			7,090.00	3,120.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (UN-CONFIRMED)				2,500.00

Report Ref No. CS3/ASM22004858/Rvy3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.