

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008825/KVY3M4**Date:** 28/04/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001961258

Claimant Vehicle No : SKC8198P**Insured Vehicle No :** SLP4034A

Date of Loss: 02/09/2022

Nature of Claim: TP

Claim No: 284389

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKC8198P**

Make & Model: KIA CERATO, 1.6 EX (A)

Engine No: G4FGJH717193

Reg. Date: 21/03/2019 (Man. Year: 2018)

Chassis No: KNAF3416MK5029629

Colour: Metallic Grey

Odometer: 49246 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Yokohama 9 mm

Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm

Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,102.41	12,831.29	6,271.12	32.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,210.00	1,890.00	4,320.00	69.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,312.41	14,721.29	10,591.12	41.84
+ GST 8.00/8.00% (S\$)	2,024.99	1,177.70	847.29	41.84
Nett Amount (S\$)	27,337.40	15,898.99	11,438.41	41.84

INSPECTION

Date of Assignment: 08/09/2022

Date Inspected: 08/09/2022 Inspected At:

ACCORD AUTO SERVICES PTE LTD
 10 ANG MO KIO INDUSTRIAL PARK 2A
 AMK AUTO POINT #03-11
 SINGAPORE 568047

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2023)
Parts:	143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC8198P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Repair	1,609.81 FL	*- FL
2	1	*FRONT BONNET HINGE	Repair	38.00 FL	*- FL
3	1	*FRONT BONNET LOCK	Distorted	92.28 FL	*92.28 FL
4	1	*FRONT BONNET SEAL (NPA)	Not Necessary	0.00 FL	*- FL
5	1	*FRONT BUMPER	Cracked	633.60 FL	*633.60 FL
6	2	*FRONT BUMPER SIDE RETAINER LH & RH	Distorted	39.64 FL	*39.64 FL
7	1	*FRONT EMBLEM	Necessary	24.55 FL	*24.55 FL
8	1	*FRONT GRILLE BASE	Cracked	34.02 FL	*34.02 FL
9	1	*FRONT GRILLE	Cracked	295.34 FL	*295.34 FL
10	1	*FRONT GRILLE CENTRE CHROME	Cracked	210.14 FL	*210.14 FL
11	1	*FRONT BUMPER LOWER GRILLE	Cracked	236.13 FL	*236.13 FL
12	1	*TOWING COVER	Serviceable	8.00 FL	*- FL
13	1	*FRONT HEADLAMP LH	Cracked	1,220.17 FL	*1,220.17 FL
14	1	*FRONT HEADLAMP LOWER BRACKET LH	Serviceable	19.82 FL	*- FL
15	1	*FRONT HEADLAMP RH	Cut	1,220.17 FL	*1,220.17 FL
16	1	*FRONT HEADLAMP LOWER BRACKET RH	Serviceable	19.82 FL	*- FL
17	1	*FRONT LH FOGLAMP	Cracked	273.18 FL	*273.18 FL
18	1	*FRONT LH FOGLAMP GARNISH	Serviceable	32.44 FL	*- FL
19	1	*FRONT RH FOGLAMP	Serviceable	273.18 FL	*- FL
20	1	*FRONT RH FOGLAMP GARNISH	Serviceable	32.44 FL	*- FL
21	1	*FRONT LH FENDER	Repair	387.30 FL	*- FL
22	1	*FRONT LH FENDER INNER SHIELD	Distorted	85.40 FL	*85.40 FL
23	1	*FRONT RH FENDER	Repair	387.30 FL	*- FL
24	1	*FRONT RH FENDER INNER SHIELD	Serviceable	85.40 FL	*- FL
25	1	*FRONT SUPPORT PANEL	Bent	608.86 FL	*608.86 FL
26	1	*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	34.02 FL	*- FL
27	1	*FRONT REINFORCEMENT BAR	Bent	448.28 FL	*448.28 FL
28	2	*FRONT REINFORCEMENT ARM	Bent	476.20 FL	*476.20 FL
29	1	*HORN	Serviceable	66.02 FL	*- FL
30	1	*RADIATOR	Bent	591.10 FL	*591.10 FL
31	1	*RADIATOR AIRDUCT CENTRE (NPA)	Serviceable	0.00 FL	*- FL
32	2	*RADIATOR AIR GUIDE LH & RH	Distorted	50.00 FL	*50.00 FL
33	1	*RADIATOR TOP STOPPER (NPA)	Serviceable	0.00 FL	*- FL
34	2	*RADIATOR LOWER STOPPER	Serviceable	14.60 FL	*- FL
35	1	*RADIATOR HOSE *TOP	Serviceable	24.30 FL	*- FL
36	1	*RADIATOR HOSE *2ND TOP	Serviceable	28.00 FL	*- FL
37	1	*RADIATOR HOSE *LOWER	Serviceable	36.00 FL	*- FL
38	1	*WASHER TANK (NPA)	Serviceable	0.00 FL	*- FL
39	1	*WASHER TANK CAP (NPA)	Serviceable	0.00 FL	*- FL
40	1	*WASHER TANK HOSE	Serviceable	24.30 FL	*- FL
41	1	*ENGINE TOP COVER (NPA)	Serviceable	0.00 FL	*- FL
42	1	*AIRCON CONDENSER	Bent	620.00 FL	*620.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
43	1	*AIRCON CONDENSER PIPE CENTRE (NPA)	Serviceable	0.00 FL	*- FL
44	1	*AIRCON CONDENSER DISCHARGE HOSE/PIPE	Serviceable	110.00 FL	*- FL
45	1	*AIRCON FAN }	Cracked	591.20 FL	*591.20 FL
46	2	*RADIATOR FAN MOTOR }	-	-	-
47	2	*RADIATOR FAN BLADE }	-	-	-
48	2	*RADIATOR FAN COWLING }	-	-	-
49	1	*ENGINE TOP COVER (NPA)	Serviceable	0.00 FL	*- FL
50	2	*AIRBAG SENSOR *FRONT	Necessary	98.00 FL	*98.00 FL
51	1	*AIRBAG CONTROL UNIT	Necessary	1,025.60 FL	*1,025.60 FL
52	1	*DASHBOARD	Torn	1,280.00 FL	*1,280.00 FL
53	1	*LH AIRBAG	Burst	1,276.00 FL	*1,276.00 FL
54	1	*RH AIRBAG	Burst	922.30 FL	*922.30 FL
55	1	*STEERING COLUMN	Serviceable	2,977.00 FL	*- FL
56	1	*STEERING ANGLE SENSOR SPRING	Necessary	228.00 FL	*228.00 FL
57	1	*LH SEAT BELT	Jammed	284.00 FL	*284.00 FL
58	1	*LH SEAT BELT BUCKLE	Serviceable	181.00 FL	*- FL
59	1	*RH SEAT BELT	Jammed	285.30 FL	*285.30 FL
60	1	*RH SEAT BELT BUCKLE	Serviceable	103.00 FL	*- FL
61	1	*FRONT WINDSCREEN	Cracked	821.13 FL	*821.13 FL
62	1	*FRONT WINDSCREEN MOULDING	Necessary	49.73 FL	*49.73 FL
63	1	*ERP BRACKET	Necessary	90.00 FS	*28.00 FS
64	1	*AIR FILTER BOX	Serviceable	156.16 FL	*- FL
65	1	*AIR DUCT	Serviceable	49.00 FL	*- FL
66	2	*AIRCON COWLING MOULDING (NPA)	Serviceable	0.00 FL	*- FL
67	1	*AMBIENT SENSOR	Serviceable	41.00 FL	*- FL
68	2	*SET CAR PLATE NUMBER WITH FRAME (FRONT & REAR)	Bent	100.00 FS	*45.00 FS
69	1	*SET FRONT BUMPER & GRILLE CLIPS	Necessary	50.00 FS	*50.00 FS
70	1	*SET FRONT BOTH SIDE FENDER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS
71	1	*SET RADIATOR TOP GARNISH & UNDER ENGINE COVER CLIPS	Not Necessary	50.00 FS	*- FS
72	1	*FRONT WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 21,178.23 14,233.32
- List Item Discount on L Items 10.00/10.00% (\$\$) 2,075.82 1,402.03

Total Parts (\$\$) 19,102.41 12,831.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,800.00	600.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	2,000.00	600.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	20.00
4	TO REPAIR/ADJUST/REALIGN FRONT MAIN CHASSIS & CROSSMEMBER	New	350.00	0.00
5	TO REMOVE/REFIX/REPLACE FRONT BOTH SELT & BUCKLE	New	200.00	0.00
6	TO REMOVE.REFIX.REPLACE THE NECESSARY ATTACHMENT IN CONNECTION LH & RH AIRBAG, UNDER STEERING AIRBAG, DASHBOARD, STEERING COLUMN, CLOCK SPRING & ETC....	New	800.00	250.00
7	TO REMOVE/REPLACE RADIATOR & AIRCON CONDENSOR (REMOVE PIPE, HOSE & ETC... TOP UP COOLANT, AIRCON GAS & ETC....	New	280.00	100.00
8	COMPUTER DIAGNOSTIC (RESET AIRBAG CONTROL UNIT & NECESSARY IN CONNECT)	New	500.00	200.00
9	TO REMOVE/REFIX/REPLACE FRONT WINDSCREEN	New	180.00	120.00
Gross Labour Cost (\$\$)			6,210.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >