



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4482E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP, LH	CUT	740.42	740.42
1	FRONT BUMPER	DEFORMED	596.00	596.00
1	FRONT BUMPER GRILLE	NOT NECESSARY	200.00	-
1	FRONT BUMPER SIDE RETAINER, LH	BROKEN	155.70	155.70
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	380.00	-
1	FRONT CONNECTOR, LH	NOT NECESSARY	192.00	-
1	FRONT RADIATOR BRACKET	NOT NECESSARY	162.50	-
1	FRONT RADIATOR GRILLE	NOT NECESSARY	520.00	-
4	FRONT RADIATOR GRILLE CLIP @\$10.00	NOT NECESSARY	40.00	-
1	FRONT FOG LAMP COVER, LH	CUT	125.50	125.50
1	RADIATOR	NOT NECESSARY	580.00	-
	LESS 25% DISCOUNT		-923.03	-404.41
			2,769.09	1,213.21
	<u>LABOUR</u>			
	REMOVE & RENEW PARTS, PANEL BEAT & RE-ALIGN FRONT LH PORTION.		1,000.00	250.00
	TO CHECK WIRING.		150.00	30.00
	TOP UP COOLANT.	NOT NECESSARY	150.00	-
	PUTTY & SPRAY PAINT FRONT BUMPER, FRONT BUMPER REINFORCEMENT & FRONT RADIATOR BRACKET.		850.00	200.00
			2,150.00	480.00
GRAND TOTAL			4,919.09	1,693.21
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,350.00

Report Ref No. CS/GAI22008830/Ecy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.