



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. ES 7117S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,745.00	-
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	48.00	-
1	FRONT HEADLAMP RH	CUT	4,230.00	3,927.00
1	FRONT HEADLAMP BRACKET RH	SERVICEABLE	261.00	-
1	FRONT FOGLAMP GARNISH	SERVICEABLE	275.00	-
1	FRONT FOGLAMP CHROME	SERVICEABLE	75.00	-
2	REVERSE SENSOR	SERVICEABLE	290.00	-
2	REVERSE SENSOR SEAL	NOT NECESSARY	120.00	-
	LESS 10% DISCOUNT		-704.40	-392.70
			6,339.60	3,534.30
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	45.00	-
			45.00	-
	<b><u>LABOUR</u></b>			
	SPRAY PAINT ON ALL AFFECTED AREA.		800.00	220.00
	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK,JACK,CUT/WELD AND REALIGN ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		800.00	180.00
	TO APPLY ANTI RUST TREATMENT.	NOT NECESSARY	120.00	-
			1,720.00	400.00
	<b>GRAND TOTAL</b>		<b>8,104.60</b>	<b>3,934.30</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>3,934.30</b>

Report Ref No. CS/AGI22008831/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.