10/5/22, 4:32 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22008834/UVY3Q2

Date: 05/10/2022

REFERENCE

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00110942102

Claimant Vehicle

XE1430A

Insured Vehicle No :

XE4328T

Date of Loss:

No:

01/09/2022

Nature of Claim: TP

Claim

SNM22D206226/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE1430A

 Make & Model:
 MITSUBISHI FV517JD2RDEB, 11.9 D (M)
 Engine No:
 6D24327760

 Reg. Date:
 29/03/2003 (Man. Year: 2002)
 Chassis No:
 FV517PA00265

 Colour:
 Green
 Odometer:
 821860 km

Engine Capacity: 11945 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D/D) Front Left Side: HILO 5 mm Rear Left Side: HILO 5/5/5/5 mm Front Right Side: HILO 5/5/5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,898.25	0.00	9,898.25	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,200.00	2,180.00	64.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,278.25	1,200.00	12,078.25	90.96
+ GST 7.00/7.00% (S\$)	929.48	84.00	845.48	90.96
Nett Amount (S\$)	14,207.73	1,284.00	12,923.73	90.96

INSPECTION

Date of Assignment: 07/09/2022

Mah Lian Motor Vehicle Repairer (HQ)

Date Inspected: 23/09/2022 Inspected At: NO. 38 DEFU LANE 9

Singapore 539278

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/5/22, 4:32 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 Oct 2022)

Parts: N/A MITSUBISHI FV517JD2RDEB 11.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE1430A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER PANEL -RH	Repair	1,098.23 FL	*- FL
2	1		*FRONT CORNER PANEL SEAL -RH	Not Necessary	196.45 FL	*- FL
3	1		*FRONT DOOR ASSY -RH	Repair	6,773.42 FL	*-FL
4	1		*FRONT DOOR GARNISH -RH	Not Necessary	220.86 FL	*-FL
5	1		*REAR CORNER PANEL -RH	Repair	2,151.31 FL	*-FL
6	1		*REAR CORNER PANEL HANDLE-RH	Not Necessary	197.60 FL	*-FL
7	1		*FRONT FENDER GARNISH -RH	Not Necessary	279.53 FL	*-FL
8	1		*FRONT FENDER -RH	Not Necessary	1,455.41 FL	*-FL
F=Fra	nchise	part. L=ListIte	mDisc.	_		
				Sub Total (S\$)	12,372.81	0.00
	- List Item Discount on L Items 20.00/20.00% (S\$)			2,474.56	0.00	
				Total Parts (S\$)	9,898.25	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO STRAIGHTENING ,KNOCKING ,WELD CUTTING ,REPAIR AND RENEW ALL DENTED PARTS	New	1,800.00	800.00
2	TO SPRAY & PAINTING AT ALL DENTED AREA	New	1,200.00	400.00
3	TO RUST PROOFING	New	380.00	0.00
	Gross Labour	Cost (S\$)	3,380.00	1,200.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >