

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008835/KVY3Q2**Date:** 14/10/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00149132102

Claimant Vehicle No : GBK1569M **Insured Vehicle No :** XD8158X

Date of Loss: 22/08/2022 Nature of Claim: TP Claim No: SNM22D206370/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK1569M**

Make & Model: MERCEDES-BENZ VITO 119, 3.2 (A) Engine No: 65195035068888

Reg. Date: 21/01/2020 (Man. Year: 2019) Chassis No: WDF44760323596929

Colour: Black Odometer: 62450 km

Engine Capacity: 2143 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Gaenlander 9 mm Rear Left Side: Gaenlander 6 mm

Front Right Side: Gaenlander 9 mm Rear Right Side: Gaenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,163.20	5,182.20	981.00	15.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,380.00	1,720.00	55.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,263.20	6,562.20	2,701.00	29.16
+ GST 7.00/7.00% (S\$)	648.42	459.35	189.07	29.16
Nett Amount (S\$)	9,911.62	7,021.55	2,890.07	29.16

INSPECTION

Date of Assignment: 08/09/2022

Date Inspected: 08/09/2022 Inspected At: Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2022)
Parts:	143	MERCEDES-BENZ VITO 119 3.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK1569M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,670.00 FN	*1,670.00 FN
2	1		*BONNET LOCK	Distorted	138.00 FN	*138.00 FN
3	2		*BONNET HINGE -RH/LH	Repair	172.00 FN	*- FN
4	1		*FRONT GRILLE CENTRE LOGO	Cracked	158.00 FN	*158.00 FN
5	1		*BRACE PANEL	Distorted	98.00 FN	*98.00 FN
6	2		*HEADLAMP ASSY -RH /LH	O/S Cracked / N/S Mtg Cracked	1,560.00 FN	*1,560.00 FN
7	1		*SUPPORT PANEL	Cracked	420.00 FN	*420.00 FN
8	2		*SUPPORT PANEL TOP BRACKET -RH/LH	Cracked	48.00 FN	*48.00 FN
9	1		*SUPPORT PANEL TOP GARNISH	Buckled	76.00 FN	*76.00 FN
10	1		*FRONT BUMPER	Bent	870.00 FN	*870.00 FN
11	1		*FRONT BUMPER REINFORCEMENT	Bent	720.00 FN	*720.00 FN
12	2		*FRONT BUMPER SIDE RETAINER -RH/LH	Serviceable	148.00 FN	*- FN
13	1		*AIR-CON CONDENSER	Serviceable	650.00 FN	*- FN
14	1		*AIR-CON CONDENSER FRAME	Serviceable	120.00 FN	*- FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	6,848.00	5,758.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	684.80	575.80
Total Parts (\$\$)	6,163.20	5,182.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT AIR-CON CONDENSER ,RADIATOR AND REFILL AIRCON GAS	New	150.00	100.00
2	TO PANEL BEAT AND STRAIGHTEN FRONT FENDER ,FRONT CHASSIS FRAME INCLUDING REPLACEMENT OF PARTS AND REALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME	New	1,000.00	500.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	250.00
5	TO RESET AND REPROGRAM HEADLAMP FAULT CODE	New	350.00	200.00
6	TO APPLY RUST PROOFING ON REPLACED AND REPAIRED PANELS	New	120.00	30.00
7	TO SUPPLY AND PASTE DECAL ON BONNET	New	400.00	280.00
Gross Labour Cost (\$\$)			3,100.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >