

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008840/KPA3Q2**Date:** 08/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100479529
Claimant Vehicle No :	SLK2821J	Insured Vehicle No :	SDW6188J
Date of Loss:	03/09/2022	Nature of Claim:	TP
		Claim No:	0582053244SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2821J		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT ABS D/AIRBAG 2WD (A)	Engine No:	L15B3538946
Reg. Date:	11/01/2017 (Man. Year: 2016)	Chassis No:	GK81007642
Colour:	Metallic Dark Blue	Odometer:	120732 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,532.24	3,176.96	355.28	10.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,440.00	190.00	11.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,162.24	4,616.96	545.28	10.56
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	5,162.24	3,700.00	1,462.24	28.33
+ GST 7.00/7.00% (S\$)	361.36	259.00	102.36	28.33
Nett Amount (S\$)	5,523.60	3,959.00	1,564.60	28.33
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,561.00		

INSPECTION

Date of Assignment:	07/09/2022	
Date Inspected:	07/09/2022	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,193.00 FL	*1,193.00 FL
2	2		*TAIL GATE GLASS SIDE MOULDING	Necessary	113.00 FL	*113.00 FL
3	1		*TAIL GATE GLASS LOWER MOULDING	Necessary	86.20 FL	*86.20 FL
4	1		*TAIL GATE SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
5	1		*TAIL GATE RUBBER (50%)	Distorted / Dented	134.40 FS	*84.00 FS
6	1		*TAIL GATE INNER LOCK	Dented	256.00 FL	*256.00 FL
7	1		*TAIL GATE OPEN POCKET	Dented	25.00 FL	*25.00 FL
8	1		*REAR END PANEL	Bent	560.00 FL	*560.00 FL
9	1		*END PANEL TOP GARNISH	Distorted	155.50 FL	*155.50 FL
10	1		*REAR BUMPER FASCIA	Buckled	1,150.60 FL	*1,072.50 FL
11	1		*REAR O/S BUMPER REFLECTOR	Serviceable	51.50 FL	*- FL
12	1		*RR O/S BUMPER REFLECTOR COVER	Serviceable	45.00 FL	*- FL
13	1		*O/S BUMPER REFLECTOR BRACKET	Repair	56.50 FL	*- FL
14	1		*REAR W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
15	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
16	1		*SET REAR BUMPER REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
					Sub Total (\$)	4,281.70 3,880.20
					- List Item Discount on L Items 20.00/20.00% (\$)	749.46 703.24
					Total Parts (\$)	3,532.24 3,176.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
3	TO APPLY UNDERSEALING	New	60.00	60.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	600.00	600.00
5	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	700.00	600.00
Gross Labour Cost (\$)			1,630.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >