

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 2199G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT HEADLAMP - RH (CONSISTENT)	SCRATCHED / CRACKED	3,617.00	3,366.07
1	FRONT HEADLAMP PANEL (CONSISTENT)	NOT NECESSARY	218.00	-
1	FRONT BUMPER (CONSISTENT)	DEEP CUT	1,887.00	1,636.54
1	FRONT BUMPER INNER FRAME (CONSISTENT)	NOT NECESSARY	199.00	-
1	SET FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	65.00	50.00
2	FRONT BUMPER SIDE MOULDINGS (CONSISTENT)	NOT NECESSARY	250.00	-
1	FRONT BUMPER SIDE GRILLE (CONSISTENT)	NOT NECESSARY	142.00	-
2	FRONT BUMPER SIDE RETAINERS (CONSISTENT)	NOT NECESSARY	151.00	-
1	FRONT BUMPER TOW HOOK COVER (CONSISTENT)	NOT NECESSARY	50.00	-
4	FRONT BUMPER PDC SENSOR (CONSISTENT)	O/S SHORTED (1PIECE ONLY)	1,432.00	182.00
1	FRONT FENDER - R (CONSISTENT)	TO REPAIR SEE LABOUR	1,085.00	-
	LESS 10% DISCOUNT		-909.60	-523.46
			8,186.40	4,711.15
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.		80.00	20.00
	TO REMOVE AND REPLACED PDC SENSOR.		180.00	40.00
	TO APPLY UNDERCOATING.	NOT NECESSARY	150.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER - R.		800.00	250.00
	TO RESPRAY PAINTING ON AFFECTED AREAS.		800.00	400.00
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.		450.00	50.00
			2,460.00	760.00
	GRAND TOTAL		10,646.40	5,471.15

RECOMMENDED COST OF LUMP SUM REPAIRS		4,300.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/ASM22008849/Uvy3m4

CHUA KANG SENG

Licensed Appraiser